

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων Πρασίνου

3ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021	2.670000
029	.151500
051	15.400000
111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.047200
212	1.300000
213	1.949500
214	3.930000
221	.099900
224	.070000
231	.775000
241	7.050000
242	5.000000
251	290.000000
252	290.000000
301	4.060000
302	6.700000
360	11.000000
361	28.200000
362	3.600000
363	.580000
364	3.520000
365	23.000000
366	21.150000
367	.121700
368	20.000000
369	12.150000
370	8.000000
371	7.200000
372	1.270000
373	2.040000
374	2.750000
375	1.500000
376	
377	3.270000
378	.540000
379	14.350000
380	.270000
401	260.720000
402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
417	130.670000

420	94.500000
428	425.280000
450	111.820000
451	154.970000
452	94.950000
453	88.120000
454	119.120000
455	420.570000

501	501				
211		50.000000 x	1.047200 =	52.360000	
214		3.000000 x	3.930000 =	11.790000	
401		1.000000 x	260.720000 =	260.720000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	545.962593

				Η.Δ. =	600.558852
502	502				
211		80.000000 x	1.047200 =	83.776000	
114		8.000000 x	23.886192 =	191.089536	
402		1.000000 x	369.270000 =	369.270000	
214		7.000000 x	3.930000 =	27.510000	
118		4.000000 x	10.001019 =	40.004076	

				ΑΘΡΟΙΣΜΑ =	711.649612

				Η.Δ. =	782.814573
503	503				
211		110.000000 x	1.047200 =	115.192000	
428		1.000000 x	425.280000 =	425.280000	
214		10.000000 x	3.930000 =	39.300000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	810.865612

				Η.Δ. =	891.952173
504	504				
211		40.000000 x	1.047200 =	41.888000	
214		2.000000 x	3.930000 =	7.860000	
114		8.000000 x	23.886192 =	191.089536	
403		1.000000 x	100.390000 =	100.390000	

				ΑΘΡΟΙΣΜΑ =	341.227536

				Η.Δ. =	375.350290
505	505				
211		200.000000 x	1.047200 =	209.440000	
214		10.000000 x	3.930000 =	39.300000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
404		1.000000 x	206.630000 =	206.630000	

				ΑΘΡΟΙΣΜΑ =	726.467688

				Η.Δ. =	799.114457

506	506				
211		95.000000 x	1.047200 =		99.484000
214		6.000000 x	3.930000 =		23.580000
405		1.000000 x	200.790000 =		200.790000
242		2.500000 x	5.000000 =		12.500000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536

			ΑΘΡΟΙΣΜΑ =		607.451688

			Η.Δ. =		668.196857
507	507				
211		165.000000 x	1.047200 =		172.788000
214		10.000000 x	3.930000 =		39.300000
242		7.000000 x	5.000000 =		35.000000
406		1.000000 x	311.770000 =		311.770000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152

			ΑΘΡΟΙΣΜΑ =		829.955688

			Η.Δ. =		912.951257
508	508				
211		40.000000 x	1.047200 =		41.888000
407		1.000000 x	53.630000 =		53.630000
115		4.000000 x	21.778427 =		87.113708
116		16.000000 x	20.419486 =		326.711776
408		2.000000 x	4.400000 =		8.800000
214		2.000000 x	3.930000 =		7.860000

			ΑΘΡΟΙΣΜΑ =		526.003484

			Η.Δ. =		578.603832
509	509				
211		80.000000 x	1.047200 =		83.776000
117		8.000000 x	16.777917 =		134.223336
409		1.000000 x	122.460000 =		122.460000
214		5.000000 x	3.930000 =		19.650000

			ΑΘΡΟΙΣΜΑ =		360.109336

			Η.Δ. =		396.120270
510	510				
211		80.000000 x	1.047200 =		83.776000
117		8.000000 x	16.777917 =		134.223336
214		5.000000 x	3.930000 =		19.650000
410		1.000000 x	113.190000 =		113.190000

			ΑΘΡΟΙΣΜΑ =		350.839336

			Η.Δ. =		385.923270

511	511				
212		17.000000 x	1.300000 =	22.100000	
411		1.000000 x	26.580000 =	26.580000	
214		1.000000 x	3.930000 =	3.930000	
115		4.000000 x	21.778427 =	87.113708	
112		30.000000 x	17.312112 =	519.363360	

				ΑΘΡΟΙΣΜΑ =	659.087068

				Η.Δ. =	724.995775
512	512				
211		10.000000 x	1.047200 =	10.472000	
115		2.000000 x	21.778427 =	43.556854	
214		1.000000 x	3.930000 =	3.930000	
112		2.000000 x	17.312112 =	34.624224	
412		1.000000 x	2.900000 =	2.900000	

				ΑΘΡΟΙΣΜΑ =	95.483078

				Η.Δ. =	105.031386
518	518				
211		180.000000 x	1.047200 =	188.496000	
212		5.000000 x	1.300000 =	6.500000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
112		8.000000 x	17.312112 =	138.496896	
417		1.000000 x	130.670000 =	130.670000	
214		12.000000 x	3.930000 =	47.160000	

				ΑΘΡΟΙΣΜΑ =	782.420584

				Η.Δ. =	860.662642
521	521				
211		40.000000 x	1.047200 =	41.888000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	3.930000 =	11.790000	
420		1.000000 x	94.500000 =	94.500000	

				ΑΘΡΟΙΣΜΑ =	379.271612

				Η.Δ. =	417.198773
550	550				
211		80.000000 x	1.047200 =	83.776000	
214		5.000000 x	3.930000 =	19.650000	
117		8.000000 x	16.777917 =	134.223336	
450		1.000000 x	111.820000 =	111.820000	

				ΑΘΡΟΙΣΜΑ =	349.469336

				Η.Δ. =	384.416270

560	560				
211		80.000000 x	1.047200 =	83.776000	
117		8.000000 x	16.777917 =	134.223336	
455		1.000000 x	420.570000 =	420.570000	
214		7.000000 x	3.930000 =	27.510000	
			AΘΡΟΙΣΜΑ =	666.079336	
			H.Δ. =	732.687270	
621	621				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	578.603832 =	2.893019	
116		.200000 x	20.419486 =	4.083897	
111		.800000 x	15.741598 =	12.593278	
			B.T =	19.765145	
623	623				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	578.603832 =	2.893019	
504		.005000 x	375.350290 =	1.876751	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
518		.010000 x	860.662642 =	8.606626	
509		.005000 x	396.120270 =	1.980601	
			B.T =	21.367057	
625	625				
213		.100000 x	1.949500 =	.194950	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
504		.005000 x	375.350290 =	1.876751	
509		.005000 x	396.120270 =	1.980601	
518		.014300 x	860.662642 =	12.307476	
508		.005000 x	578.603832 =	2.893019	
			B.T =	25.067906	
630	630				
512		.020000 x	105.031386 =	2.100628	
			B.T =	2.100628	
630.1	630.1				
510		.006000 x	385.923270 =	2.315540	
			B.T =	2.315540	

641	641			
231		.200000 x	.775000 =	.155000
251		.001500 x	290.000000 =	.435000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	290.000000 =	.725000

			B.T =	7.526243
651	651			
221		150.000000 x	.099900 =	14.985000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
509		.003600 x	396.120270 =	1.426033
509		.011100 x	396.120270 =	4.396935
511		.050000 x	724.995775 =	36.249789
630		.600000 x	2.100628 =	1.260377
625		1.000000 x	25.067906 =	25.067906
224		120.000000 x	.070000 =	8.400000

			B.T =	124.054493
652	652			
221		650.000000 x	.099900 =	64.935000
509		.011000 x	396.120270 =	4.357323
630		.320000 x	2.100628 =	.672201
625		1.000000 x	25.067906 =	25.067906
511		.050000 x	724.995775 =	36.249789
509		.001920 x	396.120270 =	.760551
112		.500000 x	17.312112 =	8.656056
111		1.500000 x	15.741598 =	23.612397

			B.T =	164.311223
1121	1121			
112		.007000 x	17.312112 =	.121185
501		.000100 x	600.558852 =	.060056
503		.002000 x	891.952173 =	1.783904

			T.E =	1.965145
1122	1122			
112		.007000 x	17.312112 =	.121185
503		.000330 x	891.952173 =	.294344
501		.000080 x	600.558852 =	.048045
505		.000600 x	799.114457 =	.479469
507		.001400 x	912.951257 =	1.278132
509		.004447 x	396.120270 =	1.761547

			T.E =	3.982721

1123A	1123A			
112		.007000 x	17.312112 =	.121185
501		.000100 x	600.558852 =	.060056
503		.002000 x	891.952173 =	1.783904
509		.005312 x	396.120270 =	2.104191
506		.001330 x	668.196857 =	.888702

			T.E =	4.958038
1123B	1123B			
509		.001487 x	396.120270 =	.589031

			T.E =	.589031
1140	1140			
112		.010000 x	17.312112 =	.173121
521		.000200 x	417.198773 =	.083440
501		.000100 x	600.558852 =	.060056

			T.E =	.316617
1610	1610			
111		.050000 x	15.741598 =	.787080
1122		.200000 x	3.982721 =	.796544
507		.000200 x	912.951257 =	.182590
501		.000100 x	600.558852 =	.060056
502		.000200 x	782.814573 =	.156563

			T.E =	1.982833
1620	1620			
112		.250000 x	17.312112 =	4.328028
1122		1.000000 x	3.982721 =	3.982721
501		.002000 x	600.558852 =	1.201118

			T.E =	9.511867
1710	1710			
360		1.000000 x	11.000000 =	11.000000
111		.250000 x	15.741598 =	3.935400
501		.000100 x	600.558852 =	.060056

			T.E =	14.995455
2111	2111			
112		.010000 x	17.312112 =	.173121
509		.005202 x	396.120270 =	2.060618
507		.001540 x	912.951257 =	1.405945
502		.002000 x	782.814573 =	1.565629
501		.000830 x	600.558852 =	.498464

			T.E =	5.703777

2112	2112			
213		.400000 x	1.949500 =	.779800
502		.002900 x	782.814573 =	2.270162
112		.250000 x	17.312112 =	4.328028
116		.250000 x	20.419486 =	5.104872
507		.002000 x	912.951257 =	1.825903
509		.004896 x	396.120270 =	1.939405
508		.004000 x	578.603832 =	2.314415

			T.E =	18.562584
2251	2251			
111		.600000 x	15.741598 =	9.444959
621		1.050000 x	19.765145 =	20.753402
112		.600000 x	17.312112 =	10.387267
509		.012432 x	396.120270 =	4.924567

			T.E =	45.510195
2252	2252			
111		1.400000 x	15.741598 =	22.038237
621		1.050000 x	19.765145 =	20.753402
113		1.400000 x	20.419486 =	28.587280
509		.012432 x	396.120270 =	4.924567

			T.E =	76.303487
2253	2253			
111		1.500000 x	15.741598 =	23.612397
621		1.050000 x	19.765145 =	20.753402
652		.020000 x	164.311223 =	3.286224
651		.250000 x	124.054493 =	31.013623
509		.012432 x	396.120270 =	4.924567
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422

			T.E =	138.101352
2254	2254			
111		.800000 x	15.741598 =	12.593278
652		.100000 x	164.311223 =	16.431122
621		.350000 x	19.765145 =	6.917801
509		.003788 x	396.120270 =	1.500504
113		1.500000 x	20.419486 =	30.629229

			T.E =	68.071934

2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.400000 x	17.312112 =	24.236957
623		.800000 x	21.367057 =	17.093646
630		.250000 x	2.100628 =	.525157
641		3.000000 x	7.526243 =	22.578729
625		.500000 x	25.067906 =	12.533953
511		.040000 x	724.995775 =	28.999831
509		.008880 x	396.120270 =	3.517548
509		.001500 x	396.120270 =	.594180
509		.005550 x	396.120270 =	2.198467
113		1.600000 x	20.419486 =	32.671178

			T.E =	174.919646
2921	2921			
301		1.000000 x	4.060000 =	4.060000
2522		.005000 x	174.919646 =	.874598
652		.002000 x	164.311223 =	.328622
113		.400000 x	20.419486 =	8.167794
111		.400000 x	15.741598 =	6.296639

			T.E =	19.727654
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	164.311223 =	1.971735
111		.600000 x	15.741598 =	9.444959
113		.800000 x	20.419486 =	16.335589

			T.E =	34.586282
5110	5110			
111		.100000 x	15.741598 =	1.574160

			T.E =	1.574160
5120	5120			
111		.080000 x	15.741598 =	1.259328

			T.E =	1.259328
5130	5130			
111		.050000 x	15.741598 =	.787080

			T.E =	.787080
5140	5140			
111		.030000 x	15.741598 =	.472248
550		.003750 x	384.416270 =	1.441561

			T.E =	1.913809

5150	5150				
111		.030000 x	15.741598 =	.472248	
550		.002500 x	384.416270 =	.961041	

			T.E =	1.433289	
5160	5160				
213		.400000 x	1.949500 =	.779800	
111		.160000 x	15.741598 =	2.518656	
508		.001500 x	578.603832 =	.867906	

			T.E =	4.166361	
5210	5210				
363		.100000 x	.580000 =	.058000	
112		.050000 x	17.312112 =	.865606	
111		.040000 x	15.741598 =	.629664	

			T.E =	1.553270	
5220	5220				
363		.100000 x	.580000 =	.058000	
112		.030000 x	17.312112 =	.519363	
111		.020000 x	15.741598 =	.314832	

			T.E =	.892195	
5230	5230				
364		1.000000 x	3.520000 =	3.520000	
112		.080000 x	17.312112 =	1.384969	

			T.E =	4.904969	
5240	5240				
112		.080000 x	17.312112 =	1.384969	

			T.E =	1.384969	
5311	5311				
111		.002000 x	15.741598 =	.031483	
630.1		.020000 x	2.315540 =	.046311	
510		.000250 x	385.923270 =	.096481	
630		.020000 x	2.100628 =	.042013	

			T.E =	.216287	

5312	5312			
111		.001300 x	15.741598 =	.020464
630.1		.020000 x	2.315540 =	.046311
510		.000163 x	385.923270 =	.062905
630		.020000 x	2.100628 =	.042013

			T.E =	.171693
5321	5321			
111		.004000 x	15.741598 =	.062966

			T.E =	.062966
5322	5322			
111		.003300 x	15.741598 =	.051947

			T.E =	.051947
5330	5330			
111		.022200 x	15.741598 =	.349463

			T.E =	.349463
5340	5340			
363		.100000 x	.580000 =	.058000
111		.003300 x	15.741598 =	.051947

			T.E =	.109947
5351	5351			
113		.005000 x	20.419486 =	.102097

			T.E =	.102097
5352	5352			
111		.005000 x	15.741598 =	.078708
113		.014000 x	20.419486 =	.285873

			T.E =	.364581
5353	5353			
111		.010000 x	15.741598 =	.157416
113		.020000 x	20.419486 =	.408390

			T.E =	.565806

5354	5354			
111		.035000 x	15.741598 =	.550956
113		.025000 x	20.419486 =	.510487

			T.E =	1.061443
5361A	5361A			
365		.003000 x	23.000000 =	.069000
630		.000300 x	2.100628 =	.000630
510		.000188 x	385.923270 =	.072554
113		.001500 x	20.419486 =	.030629

			T.E =	.172813
5361B	5361B			
366		.003000 x	21.150000 =	.063450
510		.000188 x	385.923270 =	.072554
630		.000300 x	2.100628 =	.000630
113		.001500 x	20.419486 =	.030629

			T.E =	.167263
5362A	5362A			
365		.005000 x	23.000000 =	.115000
630		.000500 x	2.100628 =	.001050
510		.000313 x	385.923270 =	.120794
113		.002500 x	20.419486 =	.051049

			T.E =	.287893
5362B	5362B			
366		.005000 x	21.150000 =	.105750
630		.000500 x	2.100628 =	.001050
510		.000313 x	385.923270 =	.120794
113		.002500 x	20.419486 =	.051049

			T.E =	.278643
5363A	5363A			
365		.003000 x	23.000000 =	.069000
113		.001000 x	20.419486 =	.020419
510		.000125 x	385.923270 =	.048240
630		.000300 x	2.100628 =	.000630

			T.E =	.138290

5363B	5363B				
366		.003000 x	21.150000 =		.063450
113		.001000 x	20.419486 =		.020419
630		.000300 x	2.100628 =		.000630
510		.000125 x	385.923270 =		.048240

			T.E =		.132740
5364A	5364A				
365		.005000 x	23.000000 =		.115000
113		.001800 x	20.419486 =		.036755
630		.000500 x	2.100628 =		.001050
510		.000225 x	385.923270 =		.086833

			T.E =		.239638
5364B	5364B				
366		.005000 x	21.150000 =		.105750
630		.000500 x	2.100628 =		.001050
510		.000225 x	385.923270 =		.086833
113		.001800 x	20.419486 =		.036755

			T.E =		.230388
5371	5371				
111		17.300000 x	15.741598 =		272.329645
111		9.600000 x	15.741598 =		151.119341

			T.E =		423.448986
5372	5372				
379		2.000000 x	14.350000 =		28.700000
510		.100000 x	385.923270 =		38.592327
630		.100000 x	2.100628 =		.210063
113		.800000 x	20.419486 =		16.335589

			T.E =		83.837979
5380	5380				
111		5.000000 x	15.741598 =		78.707990
550		.412500 x	384.416270 =		158.571711

			T.E =		237.279701
5390	5390				
111		.120000 x	15.741598 =		1.888992
111		.030000 x	15.741598 =		.472248

			T.E =		2.361240

5510	5510				
361		15.000000 x	28.200000 =	423.000000	
363		20.000000 x	.580000 =	11.600000	
362		30.000000 x	3.600000 =	108.000000	
550		.375000 x	384.416270 =	144.156101	
113		20.000000 x	20.419486 =	408.389720	
365		2.000000 x	23.000000 =	46.000000	
111		20.000000 x	15.741598 =	314.831960	

			T.E =	1,455.977781	
5521	5521				
111		1.000000 x	15.741598 =	15.741598	
630.1		10.000000 x	2.315540 =	23.155400	
510		.125000 x	385.923270 =	48.240409	
630		10.000000 x	2.100628 =	21.006280	

			T.E =	108.143687	
5522	5522				
111		1.500000 x	15.741598 =	23.612397	

			T.E =	23.612397	
5530	5530				
453		.187500 x	88.120000 =	16.522500	
111		1.000000 x	15.741598 =	15.741598	
111		1.000000 x	15.741598 =	15.741598	

			T.E =	48.005696	
5540	5540				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	15.741598 =	11.806199	

			T.E =	20.506199	
5551	5551				
111		2.000000 x	15.741598 =	31.483196	
111		1.000000 x	15.741598 =	15.741598	

			T.E =	47.224794	
5552	5552				
379		1.000000 x	14.350000 =	14.350000	
630		.100000 x	2.100628 =	.210063	
510		.050000 x	385.923270 =	19.296164	
113		.400000 x	20.419486 =	8.167794	

			T.E =	42.024021	

5560A	5560A			
365		1.000000 x	23.000000 =	23.000000
113		.800000 x	20.419486 =	16.335589
630		.100000 x	2.100628 =	.210063
510		.100000 x	385.923270 =	38.592327

			T.E =	78.137979
5560B	5560B			
366		1.000000 x	21.150000 =	21.150000
510		.100000 x	385.923270 =	38.592327
630		.100000 x	2.100628 =	.210063
113		.800000 x	20.419486 =	16.335589

			T.E =	76.287979
5570	5570			
111		.100000 x	15.741598 =	1.574160
111		.030000 x	15.741598 =	.472248

			T.E =	2.046408
5580	5580			
111		.020000 x	15.741598 =	.314832
111		.030000 x	15.741598 =	.472248

			T.E =	.787080
5610	5610			
363		15.000000 x	.580000 =	8.700000
111		30.000000 x	15.741598 =	472.247940
550		.125000 x	384.416270 =	48.052034
367		20,000.000000 x	.121700 =	2,434.000000

			T.E =	2,962.999974
5621	5621			
111		1.000000 x	15.741598 =	15.741598
630		10.000000 x	2.100628 =	21.006280
630.1		10.000000 x	2.315540 =	23.155400
510		.125000 x	385.923270 =	48.240409

			T.E =	108.143687
5622	5622			
111		1.500000 x	15.741598 =	23.612397

			T.E =	23.612397

5630	5630			
363		15.000000 x	.580000 =	8.700000
111		.750000 x	15.741598 =	11.806199

			T.E =	20.506199
5640	5640			
111		10.000000 x	15.741598 =	157.415980
111		2.000000 x	15.741598 =	31.483196

			T.E =	188.899176
5650	5650			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240
5710	5710			
362		40.000000 x	3.600000 =	144.000000
111		5.000000 x	15.741598 =	78.707990
112		1.000000 x	17.312112 =	17.312112
560		.125000 x	732.687270 =	91.585909
510		.125000 x	385.923270 =	48.240409
509		.125000 x	396.120270 =	49.515034
114		1.000000 x	23.886192 =	23.886192
380		800.000000 x	.270000 =	216.000000
363		15.000000 x	.580000 =	8.700000
377		250.000000 x	3.270000 =	817.500000
378		100.000000 x	.540000 =	54.000000

			T.E =	1,549.447645
5720	5720			
111		.500000 x	15.741598 =	7.870799
510		.062500 x	385.923270 =	24.120204
630		10.000000 x	2.100628 =	21.006280
630.1		10.000000 x	2.315540 =	23.155400

			T.E =	76.152683
5730	5730			
363		15.000000 x	.580000 =	8.700000
111		.750000 x	15.741598 =	11.806199

			T.E =	20.506199