

ΑΤΗΕ

Αναλυτικά Τιμολόγια Ηλεκτρομηχανολογικών

4ο Τρίμηνο του 2011

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

001	15.741598
002	17.312112
003	20.419486
026	.099900
036	.090700
273	1.236500
297.1	2.000000
510	3.020000
511	.620000
513	1.150000
561	2.120000
565.3	3.800000
566.3	5.050000
567.13	18.120000
571.5.1	2.410000
572.1.7	3.860000
575.3	
581.2	9.090000
582.2	25.500000
588.3	
603.3	5.340000
605.3.5	136.000000
619.2.2	44.600000
620.1	73.000000
621.1	65.000000
630.1.2	305.000000
634.1.1	90.000000
647.2	19.000000
660.1.1	16.000000
667	139.000000
671.3.8	4,200.000000
672.4.6	5,050.000000
673.1.5	5,250.000000
684.6.2	106.000000
686.1	410.000000
687.1.1	2,400.000000
703.2.2	24.900000
714.2.6	5,140.000000
715.2.9	5,098.000000
718.3.3	1,070.000000
719.1.3	1,100.000000
720.11	9.000000
729.1.2	1,040.000000
730.2.5	2.180000
732.5.30	75.000000
744.9	74,900.000000
755.10	14,190.000000
757.1.4	18,710.000000
760.1.4	4,800.000000
801.3.2	.202500
801.7.1	1.800000
812.1.2	.166400
812.2.3	1.796100
813.2.3	2.874600
816.3.2	.940900
820.5.1	.821800
820.5.4	3.008000
825.6.1	.530500
826.2.1	1.610000

835.1.2	76.500000
841.3.5	183.000000
842.3.2	77.500000
848.1.2	32.600000
852.1.6	948.000000
855.1.13	2,732.000000
858.1.2	3.060000
859.1.2	4.480000
865.13.10	19,950.000000
865.13.9	16,500.000000
865.8.3	41.000000
867.1.22	75,800.000000
871.7.4	49.520000
872.23.1	4.400000
880.1.2	.780000
885.1.2	20.000000
890.1.1	120.000000
910.2.5	9,500.000000
911.1.17	3,430.000000
912.1.5	3,694.000000
913.1.9	68.900000
914.1.8	140.000000
915.1.6	338.000000
915.3.10	13,101.000000
916.1.3	
916.2.3	
916.3.3	
917.1	7,780.000000
918.1.1	2,010.000000
920.1.1	7,479.000000
923.1.1	61.620000
923.2.1	161.400000
925.1.1	4,600.000000
931.1.5	365.000000
931.2.4	1,070.000000
932.4.2	348.000000
933.1.1	15.500000
934.1.1	324.000000
935.1.1	73.540000
950.1.1	5.600000
951.1.7	701.000000
951.2.2	12,650.000000
952.1.4	331.800000
953.1.3	26,500.000000

1	1				
026		1.100000 x	.099900 =	.109890	
297.1		1.200000 x	2.000000 =	2.400000	
582.2		1.300000 x	25.500000 =	33.150000	
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
-----					
			T.E =	84.710967	
10	10				
581.2		1.200000 x	9.090000 =	10.908000	
003		.300000 x	20.419486 =	6.125846	
001		.300000 x	15.741598 =	4.722479	
-----					
			T.E =	21.756325	
100	100				
931.1.5		1.000000 x	365.000000 =	365.000000	
003		4.000000 x	20.419486 =	81.677944	
002		6.000000 x	17.312112 =	103.872672	
-----					
			T.E =	550.550616	
101	101				
931.2.4		1.000000 x	1,070.000000 =	1,070.000000	
002		9.000000 x	17.312112 =	155.809008	
003		6.000000 x	20.419486 =	122.516916	
-----					
			T.E =	1,348.325924	
102	102				
820.5.4		1.020000 x	3.008000 =	3.068160	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	
-----					
			T.E =	10.614480	
103	103				
932.4.2		1.000000 x	348.000000 =	348.000000	
002		2.500000 x	17.312112 =	43.280280	
003		2.500000 x	20.419486 =	51.048715	
-----					
			T.E =	442.328995	
104	104				
933.1.1		1.000000 x	15.500000 =	15.500000	
003		1.200000 x	20.419486 =	24.503383	
002		1.200000 x	17.312112 =	20.774534	
-----					
			T.E =	60.777918	

105	105			
934.1.1		1.000000 x	324.000000 =	324.000000
002		2.000000 x	17.312112 =	34.624224
003		2.000000 x	20.419486 =	40.838972
-----				
			T.E =	399.463196
106	106			
951.1.7		1.030000 x	701.000000 =	722.030000
002		4.000000 x	17.312112 =	69.248448
003		4.000000 x	20.419486 =	81.677944
-----				
			T.E =	872.956392
107	107			
952.1.4		1.030000 x	331.800000 =	341.754000
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
-----				
			T.E =	379.485598
108	108			
951.2.2		1.030000 x	12,650.000000 =	13,029.500000
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
-----				
			T.E =	13,255.889588
109	109			
953.1.3		1.030000 x	26,500.000000 =	27,295.000000
003		12.000000 x	20.419486 =	245.033832
002		12.000000 x	17.312112 =	207.745344
-----				
			T.E =	27,747.779176
11	11			
603.3		1.030000 x	5.340000 =	5.500200
003		.500000 x	20.419486 =	10.209743
-----				
			T.E =	15.709943
110	110			
950.1.1		1.050000 x	5.600000 =	5.880000
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
-----				
			T.E =	13.426320

12	12				
605.3.5		1.050000 x	136.000000 =	142.800000	
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	
-----					
			T.E =	165.438959	
13	13				
619.2.2		1.030000 x	44.600000 =	45.938000	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	
-----					
			T.E =	61.030639	
14	14				
026		15.000000 x	.099900 =	1.498500	
620.1		1.000000 x	73.000000 =	73.000000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	
-----					
			T.E =	149.961696	
15	15				
621.1		1.000000 x	65.000000 =	65.000000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	
621.1		.100000 x	65.000000 =	6.500000	
-----					
			T.E =	146.963196	
16	16				
630.1.2		1.000000 x	305.000000 =	305.000000	
003		3.000000 x	20.419486 =	61.258458	
002		3.000000 x	17.312112 =	51.936336	
630.1.2		.050000 x	305.000000 =	15.250000	
-----					
			T.E =	433.444794	
17	17				
634.1.1		1.200000 x	90.000000 =	108.000000	
003		2.000000 x	20.419486 =	40.838972	
002		.200000 x	17.312112 =	3.462422	
634.1.1		.050000 x	90.000000 =	4.500000	
-----					
			T.E =	156.801394	
18	18				
647.2		1.000000 x	19.000000 =	19.000000	
003		.200000 x	20.419486 =	4.083897	
-----					
			T.E =	23.083897	

19	19				
660.1.1		1.030000 x	16.000000 =	16.480000	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
				-----	
			T.E =	24.026320	
2	2				
561		5.320000 x	2.120000 =	11.278400	
003		.600000 x	20.419486 =	12.251692	
002		.600000 x	17.312112 =	10.387267	
				-----	
			T.E =	33.917359	
20	20				
667		1.000000 x	139.000000 =	139.000000	
667		.020000 x	139.000000 =	2.780000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	
				-----	
			T.E =	292.706392	
21	21				
671.3.8		1.000000 x	4,200.000000 =	4,200.000000	
671.3.8		.100000 x	4,200.000000 =	420.000000	
002		20.000000 x	17.312112 =	346.242240	
003		20.000000 x	20.419486 =	408.389720	
				-----	
			T.E =	5,374.631960	
22	22				
672.4.6		1.000000 x	5,050.000000 =	5,050.000000	
672.4.6		.100000 x	5,050.000000 =	505.000000	
003		20.000000 x	20.419486 =	408.389720	
002		20.000000 x	17.312112 =	346.242240	
				-----	
			T.E =	6,309.631960	
23	23				
673.1.5		1.000000 x	5,250.000000 =	5,250.000000	
003		25.000000 x	20.419486 =	510.487150	
002		25.000000 x	17.312112 =	432.802800	
687.1.1		.020000 x	2,400.000000 =	48.000000	
687.1.1		1.000000 x	2,400.000000 =	2,400.000000	
673.1.5		.020000 x	5,250.000000 =	105.000000	
				-----	
			T.E =	8,746.289950	

24	24				
684.6.2		1.000000 x	106.000000 =	106.000000	
003		1.000000 x	20.419486 =	20.419486	
684.6.2		.020000 x	106.000000 =	2.120000	
002		1.000000 x	17.312112 =	17.312112	
-----					
			T.E =	145.851598	
25	25				
686.1		1.000000 x	410.000000 =	410.000000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	
686.1		.020000 x	410.000000 =	8.200000	
-----					
			T.E =	569.126392	
26	26				
703.2.2		1.020000 x	24.900000 =	25.398000	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	
-----					
			T.E =	34.830900	
27	27				
714.2.6		1.000000 x	5,140.000000 =	5,140.000000	
003		10.000000 x	20.419486 =	204.194860	
002		10.000000 x	17.312112 =	173.121120	
714.2.6		.020000 x	5,140.000000 =	102.800000	
001		5.000000 x	15.741598 =	78.707990	
-----					
			T.E =	5,698.823970	
28	28				
715.2.9		1.000000 x	5,098.000000 =	5,098.000000	
003		12.000000 x	20.419486 =	245.033832	
002		12.000000 x	17.312112 =	207.745344	
001		6.000000 x	15.741598 =	94.449588	
715.2.9		.020000 x	5,098.000000 =	101.960000	
-----					
			T.E =	5,747.188764	
29	29				
718.3.3		1.000000 x	1,070.000000 =	1,070.000000	
002		8.000000 x	17.312112 =	138.496896	
718.3.3		.050000 x	1,070.000000 =	53.500000	
003		8.000000 x	20.419486 =	163.355888	
-----					
			T.E =	1,425.352784	



3	3			
026		1.200000 x	.099900 =	.119880
588.3		1.300000 x	.000000 =	.000000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
-----				
			T.E =	
30	30			
719.1.3		1.000000 x	1,100.000000 =	1,100.000000
719.1.3		.100000 x	1,100.000000 =	110.000000
003		16.000000 x	20.419486 =	326.711776
002		16.000000 x	17.312112 =	276.993792
001		8.000000 x	15.741598 =	125.932784
-----				
			T.E =	1,939.638352
31	31			
720.11		1.020000 x	9.000000 =	9.180000
003		.300000 x	20.419486 =	6.125846
-----				
			T.E =	15.305846
32	32			
729.1.2		1.000000 x	1,040.000000 =	1,040.000000
002		2.000000 x	17.312112 =	34.624224
003		2.000000 x	20.419486 =	40.838972
729.1.2		.030000 x	1,040.000000 =	31.200000
-----				
			T.E =	1,146.663196
33	33			
757.1.4		1.000000 x	18,710.000000 =	18,710.000000
757.1.4		.050000 x	18,710.000000 =	935.500000
002		15.000000 x	17.312112 =	259.681680
003		15.000000 x	20.419486 =	306.292290
001		7.000000 x	15.741598 =	110.191186
-----				
			T.E =	20,321.665156
34	34			
273		1.000000 x	1.236500 =	1.236500
003		.300000 x	20.419486 =	6.125846
002		.300000 x	17.312112 =	5.193634
273		.100000 x	1.236500 =	.123650
-----				
			T.E =	12.679629

35	35			
730.2.5		1.050000 x	2.180000 =	2.289000
003		.120000 x	20.419486 =	2.450338
002		.120000 x	17.312112 =	2.077453
730.2.5		.250000 x	2.180000 =	.545000
-----				
			T.E =	7.361792
36	36			
732.5.30		1.050000 x	75.000000 =	78.750000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
-----				
			T.E =	93.842639
37	37			
744.9		1.000000 x	74,900.000000 =	74,900.000000
744.9		.020000 x	74,900.000000 =	1,498.000000
001		10.000000 x	15.741598 =	157.415980
002		20.000000 x	17.312112 =	346.242240
003		20.000000 x	20.419486 =	408.389720
-----				
			T.E =	77,310.047940
38	38			
755.10		1.000000 x	14,190.000000 =	14,190.000000
755.10		.020000 x	14,190.000000 =	283.800000
001		10.000000 x	15.741598 =	157.415980
002		10.000000 x	17.312112 =	173.121120
003		10.000000 x	20.419486 =	204.194860
-----				
			T.E =	15,008.531960
39	39			
760.1.4		1.000000 x	4,800.000000 =	4,800.000000
760.1.4		.050000 x	4,800.000000 =	240.000000
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201
-----				
			T.E =	5,172.060593
4	4			
565.3		1.250000 x	3.800000 =	4.750000
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692
-----				
			T.E =	27.388959

40	40			
036		3.000000 x	.090700 =	.272100
003		.450000 x	20.419486 =	9.188769
002		.450000 x	17.312112 =	7.790450
510		.350000 x	3.020000 =	1.057000
511		.250000 x	.620000 =	.155000
513		.250000 x	1.150000 =	.287500
		-----		
			T.E =	18.750819
41	41			
801.3.2		1.050000 x	.202500 =	.212625
003		.100000 x	20.419486 =	2.041949
801.3.2		.105000 x	.202500 =	.021263
002		.100000 x	17.312112 =	1.731211
		-----		
			T.E =	4.007047
42	42			
801.7.1		1.050000 x	1.800000 =	1.890000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
801.7.1		.210000 x	1.800000 =	.378000
		-----		
			T.E =	9.814320
43	43			
812.1.2		1.050000 x	.166400 =	.174720
003		.020000 x	20.419486 =	.408390
002		.020000 x	17.312112 =	.346242
		-----		
			T.E =	.929352
44	44			
812.2.3		1.050000 x	1.796100 =	1.885905
003		.060000 x	20.419486 =	1.225169
002		.060000 x	17.312112 =	1.038727
		-----		
			T.E =	4.149801
45	45			
813.2.3		1.050000 x	2.874600 =	3.018330
813.2.3		.105000 x	2.874600 =	.301833
003		.050000 x	20.419486 =	1.020974
002		.050000 x	17.312112 =	.865606
		-----		
			T.E =	5.206743

46	46			
816.3.2		.157500 x	.940900 =	.148192
816.3.2		1.050000 x	.940900 =	.987945
002		.120000 x	17.312112 =	2.077453
003		.120000 x	20.419486 =	2.450338
		-----		
			T.E =	5.663929
47	47			
820.5.1		1.050000 x	.821800 =	.862890
820.5.1		.157500 x	.821800 =	.129434
003		.140000 x	20.419486 =	2.858728
002		.140000 x	17.312112 =	2.423696
		-----		
			T.E =	6.274747
48	48			
825.6.1		1.050000 x	.530500 =	.557025
003		.100000 x	20.419486 =	2.041949
002		.100000 x	17.312112 =	1.731211
825.6.1		.157500 x	.530500 =	.083554
		-----		
			T.E =	4.413739
49	49			
826.2.1		1.000000 x	1.610000 =	1.610000
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	5.693897
5	5			
566.3		1.250000 x	5.050000 =	6.312500
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	28.951459
50	50			
842.3.2		1.000000 x	77.500000 =	77.500000
842.3.2		.030000 x	77.500000 =	2.325000
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	98.690799
51	51			
841.3.5		1.000000 x	183.000000 =	183.000000
841.3.5		.030000 x	183.000000 =	5.490000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
		-----		
			T.E =	226.221598

52	52				
835.1.2		1.050000 x	76.500000 =	80.325000	
003		3.000000 x	20.419486 =	61.258458	
002		3.000000 x	17.312112 =	51.936336	
				-----	
			T.E =	193.519794	
53	53				
848.1.2		1.020000 x	32.600000 =	33.252000	
003		.200000 x	20.419486 =	4.083897	
				-----	
			T.E =	37.335897	
54	54				
858.1.2		1.020000 x	3.060000 =	3.121200	
003		.200000 x	20.419486 =	4.083897	
				-----	
			T.E =	7.205097	
55	55				
859.1.2		1.020000 x	4.480000 =	4.569600	
003		.200000 x	20.419486 =	4.083897	
				-----	
			T.E =	8.653497	
56	56				
865.8.3		1.050000 x	41.000000 =	43.050000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	
				-----	
			T.E =	118.513196	
57	57				
865.13.9		1.020000 x	16,500.000000 =	16,830.000000	
002		25.000000 x	17.312112 =	432.802800	
003		25.000000 x	20.419486 =	510.487150	
001		10.000000 x	15.741598 =	157.415980	
				-----	
			T.E =	17,930.705930	
58	58				
867.1.22		1.000000 x	75,800.000000 =	75,800.000000	
867.1.22		.030000 x	75,800.000000 =	2,274.000000	
002		130.000000 x	17.312112 =	2,250.574560	
003		130.000000 x	20.419486 =	2,654.533180	
001		130.000000 x	15.741598 =	2,046.407740	
				-----	
			T.E =	85,025.515480	

59	59				
871.7.4		1.000000 x	49.520000 =	49.520000	
003		1.200000 x	20.419486 =	24.503383	
002		1.200000 x	17.312112 =	20.774534	
871.7.4		.020000 x	49.520000 =	.990400	
-----					
			T.E =	95.788318	
6	6				
567.13		1.300000 x	18.120000 =	23.556000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
-----					
			T.E =	61.287598	
60	60				
872.23.1		1.020000 x	4.400000 =	4.488000	
003		.600000 x	20.419486 =	12.251692	
002		.600000 x	17.312112 =	10.387267	
880.1.2		1.000000 x	.780000 =	.780000	
-----					
			T.E =	27.906959	
61	61				
885.1.2		1.000000 x	20.000000 =	20.000000	
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	
-----					
			T.E =	42.638959	
62	62				
890.1.1		1.000000 x	120.000000 =	120.000000	
890.1.1		.050000 x	120.000000 =	6.000000	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	
-----					
			T.E =	201.463196	
63	63				
910.2.5		1.000000 x	9,500.000000 =	9,500.000000	
002		50.000000 x	17.312112 =	865.605600	
001		30.000000 x	15.741598 =	472.247940	
003		50.000000 x	20.419486 =	1,020.974300	
910.2.5		.020000 x	9,500.000000 =	190.000000	
-----					
			T.E =	12,048.827840	

7	7				
571.5.1		1.400000 x	2.410000 =	3.374000	
003		.300000 x	20.419486 =	6.125846	
002		.300000 x	17.312112 =	5.193634	
-----					
			T.E =	14.693479	
8	8				
572.1.7		1.350000 x	3.860000 =	5.211000	
002		.700000 x	17.312112 =	12.118478	
003		.700000 x	20.419486 =	14.293640	
-----					
			T.E =	31.623119	
80	80				
911.1.17		1.050000 x	3,430.000000 =	3,601.500000	
002		30.000000 x	17.312112 =	519.363360	
003		30.000000 x	20.419486 =	612.584580	
-----					
			T.E =	4,733.447940	
81	81				
912.1.5		1.050000 x	3,694.000000 =	3,878.700000	
002		30.000000 x	17.312112 =	519.363360	
003		30.000000 x	20.419486 =	612.584580	
-----					
			T.E =	5,010.647940	
82	82				
913.1.9		1.200000 x	68.900000 =	82.680000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	
-----					
			T.E =	233.606392	
83	83				
914.1.8		1.100000 x	140.000000 =	154.000000	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	
-----					
			T.E =	229.463196	
84	84				
915.1.6		1.050000 x	338.000000 =	354.900000	
002		8.000000 x	17.312112 =	138.496896	
003		8.000000 x	20.419486 =	163.355888	
-----					
			T.E =	656.752784	

85	85			
915.3.10		1.050000 x	13,101.000000 =	13,756.050000
002		20.000000 x	17.312112 =	346.242240
003		20.000000 x	20.419486 =	408.389720
-----				
			T.E =	14,510.681960
86	86			
865.13.10		1.020000 x	19,950.000000 =	20,349.000000
003		40.000000 x	20.419486 =	816.779440
002		40.000000 x	17.312112 =	692.484480
-----				
			T.E =	21,858.263920
87	87			
916.1.3		1.030000 x	.000000 =	.000000
916.3.3		1.010000 x	.000000 =	.000000
916.2.3		1.020000 x	.000000 =	.000000
003		120.000000 x	20.419486 =	2,450.338320
002		120.000000 x	17.312112 =	2,077.453440
-----				
			T.E =	
88	88			
917.1		1.000000 x	7,780.000000 =	7,780.000000
917.1		.030000 x	7,780.000000 =	233.400000
918.1.1		.030000 x	2,010.000000 =	60.300000
920.1.1		.030000 x	7,479.000000 =	224.370000
923.1.1		.030000 x	61.620000 =	1.848600
003		40.000000 x	20.419486 =	816.779440
002		40.000000 x	17.312112 =	692.484480
923.2.1		.030000 x	161.400000 =	4.842000
923.2.1		1.000000 x	161.400000 =	161.400000
923.1.1		1.000000 x	61.620000 =	61.620000
920.1.1		1.000000 x	7,479.000000 =	7,479.000000
918.1.1		1.000000 x	2,010.000000 =	2,010.000000
-----				
			T.E =	19,526.044520
89	89			
852.1.6		1.000000 x	948.000000 =	948.000000
855.1.13		1.000000 x	2,732.000000 =	2,732.000000
855.1.13		.020000 x	2,732.000000 =	54.640000
925.1.1		.020000 x	4,600.000000 =	92.000000
003		60.000000 x	20.419486 =	1,225.169160
002		60.000000 x	17.312112 =	1,038.726720
925.1.1		1.000000 x	4,600.000000 =	4,600.000000
852.1.6		.020000 x	948.000000 =	18.960000
-----				
			T.E =	10,709.495880



9

9

575.3  
003  
002

1.200000 x  
.300000 x  
.300000 x

.000000 =  
20.419486 =  
17.312112 =

.000000  
6.125846  
5.193634

-----

T.E =