

ΑΤΛΣ

Αναλυτικά Τιμολόγια Λιμενικών Έργων

1ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	17.312112
115	20.419486
116	23.886192
117	10.001019
118	21.778427
119	10.001019
120	16.777917
121	16.585068
122	13.510339
123	64.260999
211	.865500
212	.984000
213	3.490000
214	1.895000
221	.098900
222	.070000
231	36.000000
232	35.000000
241	290.000000
242	370.000000
251	.559800
252	1.785000
253	3.800000
254	5.000000
255	.742500
256	3.600000
261	
262	.980000
263	.540000
311	425.280000
312	130.670000
313	200.790000
314	4.400000
315	53.630000
316	4.400000
317	122.460000
318	26.580000
319	21.440000
320	152.240000
321	207.240000
322	287.930000
323	327.890000
324	179.890000
325	308.130000
326	100.390000
327	4.400000
351	438.810000
352	372.560000
353	438.810000
354	575.700000
355	287.930000
356	47.250000
357	226.390000
358	45.580000
359	94.500000
360	99.520000

361	76.120000
362	263.460000
363	99.670000
380	552.590000
381	552.590000
382	552.590000
383	635.530000
384	1,052.620000
385	191.250000
386	504.640000
387	72.810000
388	72.810000
389	72.810000

401	401				
211		110.000000 x	.865500 =		95.205000
116		8.000000 x	23.886192 =		191.089536
117		4.000000 x	10.001019 =		40.004076
213		10.000000 x	3.490000 =		34.900000
311		1.000000 x	425.280000 =		425.280000
				ΑΘΡΟΙΣΜΑ =	786.478612
				Η.Δ. =	865.126473
402	402				
211		180.000000 x	.865500 =		155.790000
213		12.000000 x	3.490000 =		41.880000
212		5.000000 x	.984000 =		4.920000
117		8.000000 x	10.001019 =		80.008152
116		8.000000 x	23.886192 =		191.089536
112		8.000000 x	17.312112 =		138.496896
312		1.000000 x	130.670000 =		130.670000
				ΑΘΡΟΙΣΜΑ =	742.854584
				Η.Δ. =	817.140042
403	403				
211		80.000000 x	.865500 =		69.240000
313		1.000000 x	200.790000 =		200.790000
117		8.000000 x	10.001019 =		80.008152
116		8.000000 x	23.886192 =		191.089536
213		6.000000 x	3.490000 =		20.940000
254		2.500000 x	5.000000 =		12.500000
				ΑΘΡΟΙΣΜΑ =	574.567688
				Η.Δ. =	632.024457
404	404				
211		80.000000 x	.865500 =		69.240000
212		2.000000 x	.984000 =		1.968000
119		4.000000 x	10.001019 =		40.004076
118		8.000000 x	21.778427 =		174.227416
112		4.000000 x	17.312112 =		69.248448
213		5.000000 x	3.490000 =		17.450000
314		1.000000 x	4.400000 =		4.400000
				ΑΘΡΟΙΣΜΑ =	376.537940
				Η.Δ. =	414.191734

405	405				
211		40.000000 x	.865500 =		34.620000
118		4.000000 x	21.778427 =		87.113708
115		16.000000 x	20.419486 =		326.711776
316		2.000000 x	4.400000 =		8.800000
213		2.000000 x	3.490000 =		6.980000
315		1.000000 x	53.630000 =		53.630000
				ΑΘΡΟΙΣΜΑ =	517.855484
				Η.Δ. =	569.641032
406	406				
211		80.000000 x	.865500 =		69.240000
120		8.000000 x	16.777917 =		134.223336
317		1.000000 x	122.460000 =		122.460000
213		5.000000 x	3.490000 =		17.450000
				ΑΘΡΟΙΣΜΑ =	343.373336
				Η.Δ. =	377.710670
407	407				
212		17.000000 x	.984000 =		16.728000
213		1.000000 x	3.490000 =		3.490000
118		4.000000 x	21.778427 =		87.113708
112		30.000000 x	17.312112 =		519.363360
318		1.000000 x	26.580000 =		26.580000
				ΑΘΡΟΙΣΜΑ =	653.275068
				Η.Δ. =	718.602575
408	408				
211		30.000000 x	.865500 =		25.965000
320		1.000000 x	152.240000 =		152.240000
112		4.000000 x	17.312112 =		69.248448
117		4.000000 x	10.001019 =		40.004076
116		8.000000 x	23.886192 =		191.089536
213		3.000000 x	3.490000 =		10.470000
				ΑΘΡΟΙΣΜΑ =	489.017060
				Η.Δ. =	537.918766
409	409				
211		50.000000 x	.865500 =		43.275000
324		1.000000 x	179.890000 =		179.890000
213		5.000000 x	3.490000 =		17.450000
116		8.000000 x	23.886192 =		191.089536
117		4.000000 x	10.001019 =		40.004076
112		4.000000 x	17.312112 =		69.248448
				ΑΘΡΟΙΣΜΑ =	540.957060
				Η.Δ. =	595.052766

410	410				
211		100.000000 x	.865500 =	86.550000	
213		10.000000 x	3.490000 =	34.900000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
321		1.000000 x	207.240000 =	207.240000	

			ΑΘΡΟΙΣΜΑ =	629.032060	

			Η.Δ. =	691.935266	
411	411				
211		200.000000 x	.865500 =	173.100000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
325		1.000000 x	308.130000 =	308.130000	
213		20.000000 x	3.490000 =	69.800000	

			ΑΘΡΟΙΣΜΑ =	851.372060	

			Η.Δ. =	936.509266	
412	412				
211		40.000000 x	.865500 =	34.620000	
326		1.000000 x	100.390000 =	100.390000	
116		8.000000 x	23.886192 =	191.089536	
213		2.000000 x	3.490000 =	6.980000	

			ΑΘΡΟΙΣΜΑ =	333.079536	

			Η.Δ. =	366.387490	
413	413				
211		15.000000 x	.865500 =	12.982500	
213		1.500000 x	3.490000 =	5.235000	
327		1.000000 x	4.400000 =	4.400000	
118		3.000000 x	21.778427 =	65.335281	
112		3.000000 x	17.312112 =	51.936336	

			ΑΘΡΟΙΣΜΑ =	139.889117	

			Η.Δ. =	153.878029	
501	501				
211		170.000000 x	.865500 =	147.135000	
213		3.000000 x	3.490000 =	10.470000	
351		1.000000 x	438.810000 =	438.810000	
380		1.000000 x	552.590000 =	552.590000	

			ΑΘΡΟΙΣΜΑ =	1,149.005000	

			Η.Δ. =	1,263.905500	

502	502				
211		170.000000 x	.865500 =		147.135000
352		1.000000 x	372.560000 =		372.560000
381		1.000000 x	552.590000 =		552.590000
213		3.000000 x	3.490000 =		10.470000

			ΑΘΡΟΙΣΜΑ =		1,082.755000

			Η.Δ. =		1,191.030500
503	503				
211		170.000000 x	.865500 =		147.135000
382		1.000000 x	552.590000 =		552.590000
353		1.000000 x	438.810000 =		438.810000
213		3.000000 x	3.490000 =		10.470000

			ΑΘΡΟΙΣΜΑ =		1,149.005000

			Η.Δ. =		1,263.905500
504	504				
211		190.000000 x	.865500 =		164.445000
213		6.000000 x	3.490000 =		20.940000
354		1.000000 x	575.700000 =		575.700000
383		1.000000 x	635.530000 =		635.530000

			ΑΘΡΟΙΣΜΑ =		1,396.615000

			Η.Δ. =		1,536.276500
505	505				
211		1,250.000000 x	.865500 =		1,081.875000
213		7.500000 x	3.490000 =		26.175000
384		1.000000 x	1,052.620000 =		1,052.620000
355		1.000000 x	287.930000 =		287.930000

			ΑΘΡΟΙΣΜΑ =		2,448.600000

			Η.Δ. =		2,693.460000
506	506				
211		200.000000 x	.865500 =		173.100000
213		2.000000 x	3.490000 =		6.980000
385		1.000000 x	191.250000 =		191.250000
356		1.000000 x	47.250000 =		47.250000

			ΑΘΡΟΙΣΜΑ =		418.580000

			Η.Δ. =		460.438000
507	507				
211		2,100.000000 x	.865500 =		1,817.550000
386		1.000000 x	504.640000 =		504.640000
357		1.000000 x	226.390000 =		226.390000
213		35.000000 x	3.490000 =		122.150000

			ΑΘΡΟΙΣΜΑ =		2,670.730000

			Η.Δ. =		2,884.388400

508	508				
358		1.000000 x	45.580000 =	45.580000	
387		1.000000 x	72.810000 =	72.810000	

			ΑΘΡΟΙΣΜΑ =	118.390000	

			Η.Δ. =	124.309500	
509	509				
359		1.000000 x	94.500000 =	94.500000	
388		1.000000 x	72.810000 =	72.810000	

			ΑΘΡΟΙΣΜΑ =	167.310000	

			Η.Δ. =	175.675500	
510	510				
360		1.000000 x	99.520000 =	99.520000	
389		1.000000 x	72.810000 =	72.810000	

			ΑΘΡΟΙΣΜΑ =	172.330000	

			Η.Δ. =	180.946500	
511	511				
509		.800000 x	175.675500 =	140.540400	

			Η.Δ. =	140.540400	
512	512				
501		.600000 x	1,263.905500 =	758.343300	

			Η.Δ. =	758.343300	
513	513				
363		1.000000 x	99.670000 =	99.670000	
121		8.000000 x	16.585068 =	132.680544	
123		8.000000 x	64.260999 =	514.087992	
122		8.000000 x	13.510339 =	108.082712	

			Η.Δ. =	854.521248	
1111A	1111A				
214		.200000 x	1.895000 =	.379000	
511		.020000 x	140.540400 =	2.810808	
513		.020000 x	854.521248 =	17.090425	
405		.020000 x	569.641032 =	11.392821	

			Β.Τ =	31.673054	

1111B	1111B			
501		1.000000 x	1,263.905500 =	1,263.905500
506		1.000000 x	460.438000 =	460.438000
509		2.000000 x	175.675500 =	351.351000

			ΑΘΡΟΙΣΜΑ =	2,075.694500
	B.T =	.002500 x	2,075.694500 =	5.189236

1112A	1112A			
506		1.000000 x	460.438000 =	460.438000
512		1.000000 x	758.343300 =	758.343300

			ΑΘΡΟΙΣΜΑ =	1,218.781300
	B.T =	.025000 x	1,218.781300 =	30.469533

1112B	1112B			
1111B		1.000000 x	5.189236 =	5.189236

			B.T =	5.189236
1113A	1113A			
214		.200000 x	1.895000 =	.379000
405		.025000 x	569.641032 =	14.241026
112		.250000 x	17.312112 =	4.328028
513		.035000 x	854.521248 =	29.908244
511		.035000 x	140.540400 =	4.918914

			B.T =	53.775211
1113B	1113B			
1111B		1.000000 x	5.189236 =	5.189236

			B.T =	5.189236
1114A	1114A			
112		.250000 x	17.312112 =	4.328028
512		.033000 x	758.343300 =	25.025329
506		.033000 x	460.438000 =	15.194454

			B.T =	44.547811
1114B	1114B			
1111B		1.000000 x	5.189236 =	5.189236

			B.T =	5.189236

1121A	1121A			
214		.150000 x	1.895000 =	.284250
115		.500000 x	20.419486 =	10.209743
405		.020000 x	569.641032 =	11.392821

			B.T =	21.886814
1121B	1121B			
1111B		1.000000 x	5.189236 =	5.189236

			B.T =	5.189236
1122A	1122A			
506		1.000000 x	460.438000 =	460.438000
512		1.000000 x	758.343300 =	758.343300

			AΘΡΟΙΣΜΑ =	1,218.781300
	B.T =	.012500 x	1,218.781300 =	15.234766

1122B	1122B			
1111B		1.000000 x	5.189236 =	5.189236

			B.T =	5.189236
1123A	1123A			
214		.150000 x	1.895000 =	.284250
115		1.000000 x	20.419486 =	20.419486
112		.150000 x	17.312112 =	2.596817
405		.025000 x	569.641032 =	14.241026

			B.T =	37.541579
1123B	1123B			
1111B		1.000000 x	5.189236 =	5.189236

			B.T =	5.189236
1124A	1124A			
112		.150000 x	17.312112 =	2.596817
506		.020000 x	460.438000 =	9.208760
512		.020000 x	758.343300 =	15.166866

			B.T =	26.972443
1124B	1124B			
1111B		1.000000 x	5.189236 =	5.189236

			B.T =	5.189236

3110A 1

3110A 1

221		250.000000 x	.098900 =	24.725000
701	5	.250000 x	2.795059 =	.698765
701	2	.800000 x	4.472094 =	3.577675
701	2	.500000 x	4.472094 =	2.236047
630		.250000 x	3.077561 =	.769390
607		.500000 x	9.715925 =	4.857963
606		.800000 x	8.872844 =	7.098275
407		.040000 x	718.602575 =	28.744103
714		1.400000 x	7.207995 =	10.091193
113		1.200000 x	20.419486 =	24.503383
319		.020000 x	21.440000 =	.428800
112		1.200000 x	17.312112 =	20.774534

B.T =

128.505129

3110A 2

3110A 2

221		250.000000 x	.098900 =	24.725000
701	5	.250000 x	2.795059 =	.698765
701	4	.500000 x	4.192588 =	2.096294
701	2	.800000 x	4.472094 =	3.577675
630		.250000 x	3.077561 =	.769390
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534
407		.040000 x	718.602575 =	28.744103
611		.500000 x	24.258407 =	12.129204
606		.800000 x	8.872844 =	7.098275
714		1.400000 x	7.207995 =	10.091193
319		.020000 x	21.440000 =	.428800

B.T =

135.636617

3110A 3

3110A 3

221		250.000000 x	.098900 =	24.725000
701	5	.250000 x	2.795059 =	.698765
701	4	.800000 x	4.192588 =	3.354070
701	2	.500000 x	4.472094 =	2.236047
630		.250000 x	3.077561 =	.769390
610		.800000 x	20.744705 =	16.595764
607		.500000 x	9.715925 =	4.857963
407		.040000 x	718.602575 =	28.744103
714		1.400000 x	7.207995 =	10.091193
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534
319		.020000 x	21.440000 =	.428800

B.T =

137.779013

3110A 4	3110A 4			
221		250.000000 x	.098900 =	24.725000
714		1.400000 x	7.207995 =	10.091193
112		1.200000 x	17.312112 =	20.774534
113		1.200000 x	20.419486 =	24.503383
701 5		.250000 x	2.795059 =	.698765
701 4		.800000 x	4.192588 =	3.354070
701 4		.500000 x	4.192588 =	2.096294
630		.250000 x	3.077561 =	.769390
611		.500000 x	24.258407 =	12.129204
610		.800000 x	20.744705 =	16.595764
407		.040000 x	718.602575 =	28.744103
319		.020000 x	21.440000 =	.428800
			B.T =	144.910501
3110B	3110B			
713 1		1.000000 x	5.369944 =	5.369944
704		1.000000 x	10.739888 =	10.739888
			B.T =	16.109832
3120A 1	3120A 1			
3110A 1		1.000000 x	128.505129 =	128.505129
			B.T =	128.505129
3120A 2	3120A 2			
3110A 2		1.000000 x	135.636617 =	135.636617
			B.T =	135.636617
3120A 3	3120A 3			
3110A 3		1.000000 x	137.779013 =	137.779013
			B.T =	137.779013
3120A 4	3120A 4			
3110A 4		1.000000 x	144.910501 =	144.910501
			B.T =	144.910501
3120B	3120B			
713 2		1.000000 x	5.853594 =	5.853594
705		1.000000 x	11.707188 =	11.707188
			B.T =	17.560782

3210A 1	3210A 1			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.472094 =	1.431070
601		.320000 x	23.612397 =	7.555967
3110A 1		.800000 x	128.505129 =	102.804103

			B.T =	118.087780
3210A 2	3210A 2			
111		.400000 x	15.741598 =	6.296639
3110A 2		.800000 x	135.636617 =	108.509294
701 2		.320000 x	4.472094 =	1.431070
601		.320000 x	23.612397 =	7.555967

			B.T =	123.792970
3210A 3	3210A 3			
111		.400000 x	15.741598 =	6.296639
3110A 3		.800000 x	137.779013 =	110.223210
701 2		.320000 x	4.472094 =	1.431070
601		.320000 x	23.612397 =	7.555967

			B.T =	125.506887
3210A 4	3210A 4			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.472094 =	1.431070
601		.320000 x	23.612397 =	7.555967
3110A 4		.800000 x	144.910501 =	115.928401

			B.T =	131.212077
3210A 5	3210A 5			
111		.400000 x	15.741598 =	6.296639
3110A 1		.800000 x	128.505129 =	102.804103
701 2		.320000 x	4.472094 =	1.431070
609		.320000 x	19.714881 =	6.308762

			B.T =	116.840574
3210A 6	3210A 6			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.472094 =	1.431070
609		.320000 x	19.714881 =	6.308762
3110A 2		.800000 x	135.636617 =	108.509294

			B.T =	122.545765

3210A 7	3210A 7			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.472094 =	1.431070
609		.320000 x	19.714881 =	6.308762
3110A 3		.800000 x	137.779013 =	110.223210
			B.T =	124.259682
3210A 8	3210A 8			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.472094 =	1.431070
609		.320000 x	19.714881 =	6.308762
3110A 4		.800000 x	144.910501 =	115.928401
			B.T =	129.964872
3210B	3210B			
713 1		1.000000 x	5.369944 =	5.369944
704		1.000000 x	10.739888 =	10.739888
			B.T =	16.109832
3220A 1	3220A 1			
3210A 1		1.000000 x	118.087780 =	118.087780
			B.T =	118.087780
3220A 2	3220A 2			
3210A 2		1.000000 x	123.792970 =	123.792970
			B.T =	123.792970
3220A 3	3220A 3			
3210A 3		1.000000 x	125.506887 =	125.506887
			B.T =	125.506887
3220A 4	3220A 4			
3210A 4		1.000000 x	131.212077 =	131.212077
			B.T =	131.212077
3220A 5	3220A 5			
3210A 5		1.000000 x	116.840574 =	116.840574
			B.T =	116.840574

3220A 6	3220A 6			
3210A 6		1.000000 x	122.545765 =	122.545765

			B.T =	122.545765
3220A 7	3220A 7			
3210A 7		1.000000 x	124.259682 =	124.259682

			B.T =	124.259682
3220A 8	3220A 8			
3210A 8		1.000000 x	129.964872 =	129.964872

			B.T =	129.964872
3220B	3220B			
713 2		1.000000 x	5.853594 =	5.853594
705		1.000000 x	11.707188 =	11.707188

			B.T =	17.560782
3300A 1	3300A 1			
221		300.000000 x	.098900 =	29.670000
701 5		.250000 x	2.795059 =	.698765
701 2		.500000 x	4.472094 =	2.236047
701 2		.800000 x	4.472094 =	3.577675
630		.250000 x	3.077561 =	.769390
607		.500000 x	9.715925 =	4.857963
606		.800000 x	8.872844 =	7.098275
407		.040000 x	718.602575 =	28.744103
714		2.600000 x	7.207995 =	18.740787
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	21.440000 =	.857600

			B.T =	180.591892
3300A 2	3300A 2			
221		300.000000 x	.098900 =	29.670000
701 5		.250000 x	2.795059 =	.698765
701 4		.500000 x	4.192588 =	2.096294
701 2		.800000 x	4.472094 =	3.577675
630		.250000 x	3.077561 =	.769390
319		.040000 x	21.440000 =	.857600
111		2.700000 x	15.741598 =	42.502315
407		.040000 x	718.602575 =	28.744103
611		.500000 x	24.258407 =	12.129204
606		.800000 x	8.872844 =	7.098275
714		2.600000 x	7.207995 =	18.740787
113		2.000000 x	20.419486 =	40.838972

			B.T =	187.723380

3300A 3	3300A 3			
221		300.000000 x	.098900 =	29.670000
701 5		.250000 x	2.795059 =	.698765
701 4		.800000 x	4.192588 =	3.354070
701 2		.500000 x	4.472094 =	2.236047
630		.250000 x	3.077561 =	.769390
610		.800000 x	20.744705 =	16.595764
607		.500000 x	9.715925 =	4.857963
407		.040000 x	718.602575 =	28.744103
714		2.600000 x	7.207995 =	18.740787
319		.040000 x	21.440000 =	.857600
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315

B.T = 189.865776

3300A 4	3300A 4			
221		300.000000 x	.098900 =	29.670000
714		2.600000 x	7.207995 =	18.740787
319		.040000 x	21.440000 =	.857600
113		2.000000 x	20.419486 =	40.838972
701 5		.250000 x	2.795059 =	.698765
701 4		.800000 x	4.192588 =	3.354070
701 4		.500000 x	4.192588 =	2.096294
630		.250000 x	3.077561 =	.769390
611		.500000 x	24.258407 =	12.129204
610		.800000 x	20.744705 =	16.595764
407		.040000 x	718.602575 =	28.744103
111		2.700000 x	15.741598 =	42.502315

B.T = 196.997264

3300B 1	3300B 1			
713 1		1.000000 x	5.369944 =	5.369944
704		1.000000 x	10.739888 =	10.739888

B.T = 16.109832

3300B 2	3300B 2			
713 2		1.000000 x	5.853594 =	5.853594
705		1.000000 x	11.707188 =	11.707188

B.T = 17.560782

3400A 1

3400A 1

221		300.000000 x	.098900 =	29.670000
701	5	.250000 x	2.795059 =	.698765
701	2	.800000 x	4.472094 =	3.577675
701	2	.500000 x	4.472094 =	2.236047
630		.250000 x	3.077561 =	.769390
607		.500000 x	9.715925 =	4.857963
606		.800000 x	8.872844 =	7.098275
407		.040000 x	718.602575 =	28.744103
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	21.440000 =	.643200
255		5.000000 x	.742500 =	3.712500

B.T =

192.871060

3400A 2

3400A 2

221		300.000000 x	.098900 =	29.670000
113		2.000000 x	20.419486 =	40.838972
701	5	.250000 x	2.795059 =	.698765
701	4	.500000 x	4.192588 =	2.096294
701	2	.800000 x	4.472094 =	3.577675
630		.250000 x	3.077561 =	.769390
611		.500000 x	24.258407 =	12.129204
606		.800000 x	8.872844 =	7.098275
407		.040000 x	718.602575 =	28.744103
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	21.440000 =	.643200
255		5.000000 x	.742500 =	3.712500

B.T =

200.002548

3400A 3

3400A 3

221		300.000000 x	.098900 =	29.670000
255		5.000000 x	.742500 =	3.712500
319		.030000 x	21.440000 =	.643200
701	5	.250000 x	2.795059 =	.698765
701	4	.800000 x	4.192588 =	3.354070
701	2	.500000 x	4.472094 =	2.236047
630		.250000 x	3.077561 =	.769390
610		.800000 x	20.744705 =	16.595764
607		.500000 x	9.715925 =	4.857963
407		.040000 x	718.602575 =	28.744103
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315

B.T =

202.144944

3400A 4	3400A 4			
221		300.000000 x	.098900 =	29.670000
111		2.700000 x	15.741598 =	42.502315
255		5.000000 x	.742500 =	3.712500
113		.500000 x	20.419486 =	10.209743
701 5		.250000 x	2.795059 =	.698765
701 4		.800000 x	4.192588 =	3.354070
701 4		.500000 x	4.192588 =	2.096294
630		.250000 x	3.077561 =	.769390
611		.500000 x	24.258407 =	12.129204
610		.800000 x	20.744705 =	16.595764
407		.040000 x	718.602575 =	28.744103
113		2.000000 x	20.419486 =	40.838972
319		.030000 x	21.440000 =	.643200
112		1.000000 x	17.312112 =	17.312112

			B.T =	209.276432
3400B 1	3400B 1			
704		1.000000 x	10.739888 =	10.739888

			B.T =	10.739888
3400B 2	3400B 2			
705		1.000000 x	11.707188 =	11.707188

			B.T =	11.707188
4110A 1	4110A 1			
221		350.000000 x	.098900 =	34.615000
113		1.500000 x	20.419486 =	30.629229
407		.070000 x	718.602575 =	50.302180
606		.800000 x	8.872844 =	7.098275
607		.500000 x	9.715925 =	4.857963
701 5		.100000 x	2.795059 =	.279506
701 2		.800000 x	4.472094 =	3.577675
701 2		.500000 x	4.472094 =	2.236047
630		.100000 x	3.077561 =	.307756
111		4.000000 x	15.741598 =	62.966392

			B.T =	196.870023

4110A 2	4110A 2			
221		350.000000 x	.098900 =	34.615000
407		.070000 x	718.602575 =	50.302180
701 5		.100000 x	2.795059 =	.279506
701 4		.500000 x	4.192588 =	2.096294
701 2		.800000 x	4.472094 =	3.577675
630		.100000 x	3.077561 =	.307756
611		.500000 x	24.258407 =	12.129204
606		.800000 x	8.872844 =	7.098275
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

B.T = 204.001511

4110A 3	4110A 3			
221		350.000000 x	.098900 =	34.615000
701 5		.100000 x	2.795059 =	.279506
701 4		.800000 x	4.192588 =	3.354070
701 2		.500000 x	4.472094 =	2.236047
630		.100000 x	3.077561 =	.307756
610		.800000 x	20.744705 =	16.595764
607		.500000 x	9.715925 =	4.857963
407		.070000 x	718.602575 =	50.302180
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

B.T = 206.143907

4110A 4	4110A 4			
221		350.000000 x	.098900 =	34.615000
407		.070000 x	718.602575 =	50.302180
611		.500000 x	24.258407 =	12.129204
701 5		.100000 x	2.795059 =	.279506
701 4		.800000 x	4.192588 =	3.354070
701 4		.500000 x	4.192588 =	2.096294
630		.100000 x	3.077561 =	.307756
610		.800000 x	20.744705 =	16.595764
111		4.000000 x	15.741598 =	62.966392
113		1.500000 x	20.419486 =	30.629229

B.T = 213.275395

4110B	4110B			
112		8.000000 x	17.312112 =	138.496896
513		1.000000 x	854.521248 =	854.521248
508		1.000000 x	124.309500 =	124.309500
506		1.000000 x	460.438000 =	460.438000

B.T = 1,577.765644

4120A 1	4120A 1			
221		350.000000 x	.098900 =	34.615000
701 2		1.200000 x	4.472094 =	5.366513
607		1.200000 x	9.715925 =	11.659110
112		5.000000 x	17.312112 =	86.560560
263		42.000000 x	.540000 =	22.680000

B.T = 160.881183

4120A 2	4120A 2			
221		350.000000 x	.098900 =	34.615000
701 4		1.200000 x	4.192588 =	5.031106
611		1.200000 x	24.258407 =	29.110088
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	17.312112 =	86.560560

B.T = 177.996754

4120B	4120B			
4110B		.040000 x	1,577.765644 =	63.110626

B.T = 63.110626

4130A 1	4130A 1			
221		350.000000 x	.098900 =	34.615000
111		2.000000 x	15.741598 =	31.483196
701 2		.500000 x	4.472094 =	2.236047
701 2		.800000 x	4.472094 =	3.577675
607		.500000 x	9.715925 =	4.857963
606		.800000 x	8.872844 =	7.098275
407		.050000 x	718.602575 =	35.930129
263		42.000000 x	.540000 =	22.680000

B.T = 142.478285

4130A 2	4130A 2			
221		350.000000 x	.098900 =	34.615000
111		2.000000 x	15.741598 =	31.483196
407		.050000 x	718.602575 =	35.930129
606		.800000 x	8.872844 =	7.098275
701 4		.500000 x	4.192588 =	2.096294
701 2		.800000 x	4.472094 =	3.577675
611		.500000 x	24.258407 =	12.129204
263		42.000000 x	.540000 =	22.680000

B.T = 149.609773

4130A 3	4130A 3			
221		350.000000 x	.098900 =	34.615000
263		42.000000 x	.540000 =	22.680000
701 4		.800000 x	4.192588 =	3.354070
701 2		.500000 x	4.472094 =	2.236047
610		.800000 x	20.744705 =	16.595764
607		.500000 x	9.715925 =	4.857963
407		.050000 x	718.602575 =	35.930129
111		2.000000 x	15.741598 =	31.483196

B.T = 151.752169

4130A 4	4130A 4			
221		350.000000 x	.098900 =	34.615000
701 4		.500000 x	4.192588 =	2.096294
701 4		.800000 x	4.192588 =	3.354070
611		.500000 x	24.258407 =	12.129204
610		.800000 x	20.744705 =	16.595764
407		.050000 x	718.602575 =	35.930129
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.540000 =	22.680000

B.T = 158.883657

4130B	4130B			
4120B		1.000000 x	63.110626 =	63.110626

B.T = 63.110626

4210A 1	4210A 1			
221		65.000000 x	.098900 =	6.428500
701 5		.150000 x	2.795059 =	.419259
701 2		.300000 x	4.472094 =	1.341628
701 2		1.050000 x	4.472094 =	4.695699
630		.150000 x	3.077561 =	.461634
607		.300000 x	9.715925 =	2.914778
601		1.050000 x	23.612397 =	24.793017
222		10.000000 x	.070000 =	.700000

B.T = 41.754514

4210A 2	4210A 2			
221		65.000000 x	.098900 =	6.428500
701 5		.150000 x	2.795059 =	.419259
701 4		.300000 x	4.192588 =	1.257776
630		.150000 x	3.077561 =	.461634
611		.300000 x	24.258407 =	7.277522
601		1.050000 x	23.612397 =	24.793017
701 2		1.050000 x	4.472094 =	4.695699
222		10.000000 x	.070000 =	.700000

B.T = 46.033407

4210A 3	4210A 3			
221		65.000000 x	.098900 =	6.428500
607		.300000 x	9.715925 =	2.914778
701 5		.150000 x	2.795059 =	.419259
701 2		.300000 x	4.472094 =	1.341628
701 2		1.050000 x	4.472094 =	4.695699
630		.150000 x	3.077561 =	.461634
609		1.050000 x	19.714881 =	20.700625
222		10.000000 x	.070000 =	.700000

B.T = 37.662122

4210A 4	4210A 4			
221		65.000000 x	.098900 =	6.428500
222		10.000000 x	.070000 =	.700000
701 2		1.050000 x	4.472094 =	4.695699
701 5		.150000 x	2.795059 =	.419259
701 4		.300000 x	4.192588 =	1.257776
609		1.050000 x	19.714881 =	20.700625
630		.150000 x	3.077561 =	.461634
611		.300000 x	24.258407 =	7.277522

B.T = 41.941015

4210B	4210B			
111		4.000000 x	15.741598 =	62.966392
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422
112		1.500000 x	17.312112 =	25.968168

B.T = 143.445697

4220A 1	4220A 1			
221		200.000000 x	.098900 =	19.780000
701 2		.800000 x	4.472094 =	3.577675
701 2		.500000 x	4.472094 =	2.236047
630		.250000 x	3.077561 =	.769390
607		.500000 x	9.715925 =	4.857963
606		.800000 x	8.872844 =	7.098275
407		.040000 x	718.602575 =	28.744103
113		1.000000 x	20.419486 =	20.419486
111		1.200000 x	15.741598 =	18.889918
701 5		.250000 x	2.795059 =	.698765

B.T = 107.071622

4220A 2	4220A 2			
221		200.000000 x	.098900 =	19.780000
111		1.200000 x	15.741598 =	18.889918
113		1.000000 x	20.419486 =	20.419486
611		.500000 x	24.258407 =	12.129204
701 5		.250000 x	2.795059 =	.698765
701 4		.500000 x	4.192588 =	2.096294
701 2		.800000 x	4.472094 =	3.577675
630		.250000 x	3.077561 =	.769390
606		.800000 x	8.872844 =	7.098275
407		.040000 x	718.602575 =	28.744103

B.T = 114.203110

4220A 3	4220A 3			
221		200.000000 x	.098900 =	19.780000
701 5		.250000 x	2.795059 =	.698765
701 4		.800000 x	4.192588 =	3.354070
701 2		.500000 x	4.472094 =	2.236047
630		.250000 x	3.077561 =	.769390
610		.800000 x	20.744705 =	16.595764
607		.500000 x	9.715925 =	4.857963
111		1.200000 x	15.741598 =	18.889918
407		.040000 x	718.602575 =	28.744103
113		1.000000 x	20.419486 =	20.419486

B.T = 116.345506

4220A 4	4220A 4			
221		200.000000 x	.098900 =	19.780000
111		1.200000 x	15.741598 =	18.889918
407		.040000 x	718.602575 =	28.744103
611		.500000 x	24.258407 =	12.129204
701 4		.500000 x	4.192588 =	2.096294
701 5		.250000 x	2.795059 =	.698765
701 4		.800000 x	4.192588 =	3.354070
630		.250000 x	3.077561 =	.769390
610		.800000 x	20.744705 =	16.595764
113		1.000000 x	20.419486 =	20.419486

B.T = 123.476994

4300A 1

4300A 1

221		350.000000 x	.098900 =	34.615000
701	5	.250000 x	2.795059 =	.698765
701	2	.800000 x	4.472094 =	3.577675
701	2	.500000 x	4.472094 =	2.236047
630		.250000 x	3.077561 =	.769390
607		.500000 x	9.715925 =	4.857963
606		.800000 x	8.872844 =	7.098275
407		.040000 x	718.602575 =	28.744103
714		1.150000 x	7.207995 =	8.289194
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196

ΑΘΡΟΙΣΜΑ =

146.872991

B.T =

.200000 x

146.872991 =

29.374598

4300A 2

4300A 2

221		350.000000 x	.098900 =	34.615000
611		.500000 x	24.258407 =	12.129204
701	5	.250000 x	2.795059 =	.698765
701	4	.500000 x	4.192588 =	2.096294
701	2	.800000 x	4.472094 =	3.577675
630		.250000 x	3.077561 =	.769390
606		.800000 x	8.872844 =	7.098275
407		.040000 x	718.602575 =	28.744103
714		1.150000 x	7.207995 =	8.289194
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196

ΑΘΡΟΙΣΜΑ =

154.004479

B.T =

.200000 x

154.004479 =

30.800896

4300A 3

4300A 3

221		350.000000 x	.098900 =	34.615000
111		2.000000 x	15.741598 =	31.483196
113		1.200000 x	20.419486 =	24.503383
701	5	.250000 x	2.795059 =	.698765
701	4	.800000 x	4.192588 =	3.354070
701	2	.500000 x	4.472094 =	2.236047
630		.250000 x	3.077561 =	.769390
610		.800000 x	20.744705 =	16.595764
607		.500000 x	9.715925 =	4.857963
407		.040000 x	718.602575 =	28.744103
714		1.150000 x	7.207995 =	8.289194

ΑΘΡΟΙΣΜΑ =

156.146875

B.T =

.200000 x

156.146875 =

31.229375

4300A 4	4300A 4			
221		350.000000 x	.098900 =	34.615000
701 5		.250000 x	2.795059 =	.698765
701 4		.800000 x	4.192588 =	3.354070
701 4		.500000 x	4.192588 =	2.096294
630		.250000 x	3.077561 =	.769390
611		.500000 x	24.258407 =	12.129204
610		.800000 x	20.744705 =	16.595764
407		.040000 x	718.602575 =	28.744103
111		2.000000 x	15.741598 =	31.483196
714		1.150000 x	7.207995 =	8.289194
113		1.200000 x	20.419486 =	24.503383

			ΑΘΡΟΙΣΜΑ =	163.278363
	B.T =	.200000 x	163.278363 =	32.655673

4300B	4300B			
221		2.000000 x	.098900 =	.197800
262		4.000000 x	.980000 =	3.920000
112		.400000 x	17.312112 =	6.924845

			B.T =	11.042645
601	601			
111		1.500000 x	15.741598 =	23.612397

			B.T =	23.612397
602	602			
403		.002500 x	632.024457 =	1.580061

			B.T =	1.580061
603	603			
111		.300000 x	15.741598 =	4.722479
412		.003300 x	366.387490 =	1.209079
401		.001000 x	865.126473 =	.865126

			B.T =	6.796685
604	604			
111		.200000 x	15.741598 =	3.148320
412		.004000 x	366.387490 =	1.465550
404		.005000 x	414.191734 =	2.070959
401		.001100 x	865.126473 =	.951639

			B.T =	7.636467

605	605				
112		.100000 x	17.312112 =	1.731211	
401		.001000 x	865.126473 =	.865126	
406		.006200 x	377.710670 =	2.341806	
412		.004000 x	366.387490 =	1.465550	
402		.006200 x	817.140042 =	5.066268	

				B.T =	11.469962
606	606				
111		.100000 x	15.741598 =	1.574160	
404		.005000 x	414.191734 =	2.070959	
412		.005000 x	366.387490 =	1.831937	
406		.006700 x	377.710670 =	2.530661	
401		.001000 x	865.126473 =	.865126	

				B.T =	8.872844
607	607				
111		.100000 x	15.741598 =	1.574160	
412		.005000 x	366.387490 =	1.831937	
406		.006700 x	377.710670 =	2.530661	
404		.006200 x	414.191734 =	2.567989	
401		.001400 x	865.126473 =	1.211177	

				B.T =	9.715925
608	608				
111		.100000 x	15.741598 =	1.574160	
401		.002000 x	865.126473 =	1.730253	
404		.012500 x	414.191734 =	5.177397	
412		.005000 x	366.387490 =	1.831937	
406		.006700 x	377.710670 =	2.530661	

				B.T =	12.844408
609	609				
214		.100000 x	1.895000 =	.189500	
111		.800000 x	15.741598 =	12.593278	
405		.005000 x	569.641032 =	2.848205	
115		.200000 x	20.419486 =	4.083897	

				B.T =	19.714881

610	610				
214		.100000 x	1.895000 =	.189500	
412		.005000 x	366.387490 =	1.831937	
406		.005000 x	377.710670 =	1.888553	
405		.005000 x	569.641032 =	2.848205	
402		.010000 x	817.140042 =	8.171400	
115		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
			B.T =	20.744705	
611	611				
214		.100000 x	1.895000 =	.189500	
412		.005000 x	366.387490 =	1.831937	
406		.005000 x	377.710670 =	1.888553	
405		.005000 x	569.641032 =	2.848205	
402		.014300 x	817.140042 =	11.685103	
112		.100000 x	17.312112 =	1.731211	
115		.200000 x	20.419486 =	4.083897	
			B.T =	24.258407	
612	612				
214		.150000 x	1.895000 =	.284250	
111		.300000 x	15.741598 =	4.722479	
408		.010000 x	537.918766 =	5.379188	
405		.005000 x	569.641032 =	2.848205	
115		.200000 x	20.419486 =	4.083897	
			AΘΡΟΙΣΜΑ =	17.318019	
	B.T =	1.068000 x	17.318019 =	18.495645	
613	613				
214		.150000 x	1.895000 =	.284250	
111		.500000 x	15.741598 =	7.870799	
405		.005000 x	569.641032 =	2.848205	
409		.010000 x	595.052766 =	5.950528	
115		.200000 x	20.419486 =	4.083897	
			AΘΡΟΙΣΜΑ =	21.037679	
	B.T =	1.282000 x	21.037679 =	26.970305	
614	614				
214		.150000 x	1.895000 =	.284250	
111		.500000 x	15.741598 =	7.870799	
410		.010000 x	691.935266 =	6.919353	
405		.005000 x	569.641032 =	2.848205	
115		.200000 x	20.419486 =	4.083897	
			AΘΡΟΙΣΜΑ =	22.006504	
	B.T =	1.602000 x	22.006504 =	35.254419	

615	615				
214		.150000 x	1.895000 =	.284250	
410		.010000 x	691.935266 =	6.919353	
405		.005000 x	569.641032 =	2.848205	
115		.200000 x	20.419486 =	4.083897	
111		.700000 x	15.741598 =	11.019119	

			ΑΘΡΟΙΣΜΑ =	25.154824	
	B.T =	1.832000 x	25.154824 =	46.083637	

616	616				
214		.150000 x	1.895000 =	.284250	
411		.010000 x	936.509266 =	9.365093	
405		.005000 x	569.641032 =	2.848205	
115		.200000 x	20.419486 =	4.083897	
111		.800000 x	15.741598 =	12.593278	

			ΑΘΡΟΙΣΜΑ =	29.174723	
	B.T =	2.137000 x	29.174723 =	62.346384	

617	617				
112		4.000000 x	17.312112 =	69.248448	
503		1.000000 x	1,263.905500 =	1,263.905500	
506		1.000000 x	460.438000 =	460.438000	
513		1.000000 x	854.521248 =	854.521248	

			ΑΘΡΟΙΣΜΑ =	2,648.113196	
	B.T =	.006250 x	2,648.113196 =	16.550707	

618	618				
112		4.000000 x	17.312112 =	69.248448	
506		1.000000 x	460.438000 =	460.438000	
513		1.000000 x	854.521248 =	854.521248	
503		1.000000 x	1,263.905500 =	1,263.905500	

			ΑΘΡΟΙΣΜΑ =	2,648.113196	
	B.T =	.007700 x	2,648.113196 =	20.390472	

619	619				
112		4.000000 x	17.312112 =	69.248448	
513		1.000000 x	854.521248 =	854.521248	
506		1.000000 x	460.438000 =	460.438000	
503		1.000000 x	1,263.905500 =	1,263.905500	

			ΑΘΡΟΙΣΜΑ =	2,648.113196	
	B.T =	.010000 x	2,648.113196 =	26.481132	

620	620			
112		4.000000 x	17.312112 =	69.248448
513		1.000000 x	854.521248 =	854.521248
506		1.000000 x	460.438000 =	460.438000
503		1.000000 x	1,263.905500 =	1,263.905500

			ΑΘΡΟΙΣΜΑ =	2,648.113196
	B.T =	.012500 x	2,648.113196 =	33.101415

621	621			
112		4.000000 x	17.312112 =	69.248448
503		1.000000 x	1,263.905500 =	1,263.905500
513		1.000000 x	854.521248 =	854.521248
506		1.000000 x	460.438000 =	460.438000

			ΑΘΡΟΙΣΜΑ =	2,648.113196
	B.T =	.016600 x	2,648.113196 =	43.958679

630	630			
413		.020000 x	153.878029 =	3.077561

			B.T =	3.077561
701 1	701 1			
406		.012580 x	377.710670 =	4.751600

			B.T =	4.751600
701 2	701 2			
406		.011840 x	377.710670 =	4.472094

			B.T =	4.472094
701 3	701 3			
406		.011544 x	377.710670 =	4.360292

			B.T =	4.360292
701 4	701 4			
406		.011100 x	377.710670 =	4.192588

			B.T =	4.192588
701 5	701 5			
406		.007400 x	377.710670 =	2.795059

			B.T =	2.795059

702	702				
112		8.000000 x	17.312112 =		138.496896
513		.300000 x	854.521248 =		256.356374
509		2.000000 x	175.675500 =		351.351000
506		1.000000 x	460.438000 =		460.438000
			AΘΡΟΙΣΜΑ =		1,206.642270
	B.T =	.002500 x	1,206.642270 =		3.016606
703	703				
112		4.000000 x	17.312112 =		69.248448
503		1.000000 x	1,263.905500 =		1,263.905500
506		1.000000 x	460.438000 =		460.438000
513		.300000 x	854.521248 =		256.356374
510		2.000000 x	180.946500 =		361.893000
			AΘΡΟΙΣΜΑ =		2,411.841322
	B.T =	.002500 x	2,411.841322 =		6.029603
704	704				
112		4.000000 x	17.312112 =		69.248448
502		1.000000 x	1,191.030500 =		1,191.030500
513		.500000 x	854.521248 =		427.260624
506		1.000000 x	460.438000 =		460.438000
			AΘΡΟΙΣΜΑ =		2,147.977572
	B.T =	.005000 x	2,147.977572 =		10.739888
705	705				
112		4.000000 x	17.312112 =		69.248448
504		1.000000 x	1,536.276500 =		1,536.276500
513		.600000 x	854.521248 =		512.712749
506		1.000000 x	460.438000 =		460.438000
			AΘΡΟΙΣΜΑ =		2,578.675697
	B.T =	.004540 x	2,578.675697 =		11.707188
706	706				
501		1.000000 x	1,263.905500 =		1,263.905500
509		2.000000 x	175.675500 =		351.351000
506		1.000000 x	460.438000 =		460.438000
			AΘΡΟΙΣΜΑ =		2,075.694500
	B.T =	.002500 x	2,075.694500 =		5.189236
707	707				
505		1.000000 x	2,693.460000 =		2,693.460000
506		1.000000 x	460.438000 =		460.438000
510		2.000000 x	180.946500 =		361.893000
			AΘΡΟΙΣΜΑ =		3,515.791000
	B.T =	.001000 x	3,515.791000 =		3.515791

ΑΤΛΕ		1ο Τρίμηνο του 2010		Σελ.	31
				Ημ/νία	16/06/2011
708	708				
708A		1.000000 x	17.165879 =		17.165879
708B		1.000000 x	5.189236 =		5.189236

			B.T =		22.355115
708A	708A				
214		.050000 x	1.895000 =		.094750
511		.010000 x	140.540400 =		1.405404
513		.010000 x	854.521248 =		8.545212
405		.012500 x	569.641032 =		7.120513

			B.T =		17.165879
708B	708B				
706		1.000000 x	5.189236 =		5.189236

			B.T =		5.189236
709	709				
709A		1.000000 x	15.234766 =		15.234766
709B		1.000000 x	5.189236 =		5.189236

			B.T =		20.424002
709A	709A				
506		1.000000 x	460.438000 =		460.438000
512		1.000000 x	758.343300 =		758.343300

			AΘΡΟΙΣΜΑ =		1,218.781300
	B.T =	.012500 x	1,218.781300 =		15.234766

709B	709B				
706		1.000000 x	5.189236 =		5.189236

			B.T =		5.189236
710	710				
710A		1.000000 x	49.447183 =		49.447183
710B		1.000000 x	5.189236 =		5.189236

			B.T =		54.636419
710A	710A				
214		.200000 x	1.895000 =		.379000
513		.035000 x	854.521248 =		29.908244
511		.035000 x	140.540400 =		4.918914
405		.025000 x	569.641032 =		14.241026

			B.T =		49.447183

710B	710B			
706		1.000000 x	5.189236 =	5.189236

			B.T =	5.189236
711	711			
711A		1.000000 x	40.585417 =	40.585417
711B		1.000000 x	5.189236 =	5.189236

			B.T =	45.774653
711A	711A			
506		1.000000 x	460.438000 =	460.438000
512		1.000000 x	758.343300 =	758.343300

			AΘΡΟΙΣΜΑ =	1,218.781300
	B.T =	.033300 x	1,218.781300 =	40.585417

711B	711B			
706		1.000000 x	5.189236 =	5.189236

			B.T =	5.189236
712	712			
513		1.000000 x	854.521248 =	854.521248

			AΘΡΟΙΣΜΑ =	854.521248
	B.T =	.004000 x	854.521248 =	3.418085

713 1	713 1			
704		.500000 x	10.739888 =	5.369944

			B.T =	5.369944
713 2	713 2			
705		.500000 x	11.707188 =	5.853594

			B.T =	5.853594
714	714			
714A		1.000000 x	3.434835 =	3.434835
714B		1.000000 x	3.773160 =	3.773160

			B.T =	7.207995

714A	714A			
242		.070000 x	370.000000 =	25.900000
113		2.000000 x	20.419486 =	40.838972
114		2.000000 x	17.312112 =	34.624224
252		1.000000 x	1.785000 =	1.785000
			AΘΡΟΙΣΜΑ =	103.148196
	B.T =	.033300 x	103.148196 =	3.434835
714B	714B			
113		.100000 x	20.419486 =	2.041949
114		.100000 x	17.312112 =	1.731211
			B.T =	3.773160
1111	1111			
1111A		1.000000 x	31.673054 =	31.673054
1111B		1.000000 x	5.189236 =	5.189236
			T.E =	36.862290
1112	1112			
1112A		1.000000 x	30.469533 =	30.469533
1112B		1.000000 x	5.189236 =	5.189236
			T.E =	35.658769
1113	1113			
1113A		1.000000 x	53.775211 =	53.775211
1113B		1.000000 x	5.189236 =	5.189236
			T.E =	58.964447
1114	1114			
1114A		1.000000 x	44.547811 =	44.547811
1114B		1.000000 x	5.189236 =	5.189236
			T.E =	49.737047
1121	1121			
1121A		1.000000 x	21.886814 =	21.886814
1121B		1.000000 x	5.189236 =	5.189236
			T.E =	27.076050
1122	1122			
1122A		1.000000 x	15.234766 =	15.234766
1122B		1.000000 x	5.189236 =	5.189236
			T.E =	20.424002

1123	1123				
1123A		1.000000 x	37.541579 =		37.541579
1123B		1.000000 x	5.189236 =		5.189236

			T.E =		42.730815
1124	1124				
1124A		1.000000 x	26.972443 =		26.972443
1124B		1.000000 x	5.189236 =		5.189236

			T.E =		32.161679
1210	1210				
707		1.000000 x	3.515791 =		3.515791

			T.E =		3.515791
1220	1220				
708		1.000000 x	22.355115 =		22.355115

			T.E =		22.355115
1230	1230				
709		1.000000 x	20.424002 =		20.424002

			T.E =		20.424002
1311	1311				
712		.250000 x	3.418085 =		.854521

			T.E =		.854521
1312	1312				
712		.250000 x	3.418085 =		.854521
701 1		1.000000 x	4.751600 =		4.751600
602		1.000000 x	1.580061 =		1.580061

			T.E =		7.186182
1313	1313				
712		.250000 x	3.418085 =		.854521
603		1.000000 x	6.796685 =		6.796685
701 2		1.000000 x	4.472094 =		4.472094

			T.E =		12.123300

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.741598 =	1.574160	
712		.250000 x	3.418085 =	.854521	

			T.E =	37.428681	
1321	1321				
112		.200000 x	17.312112 =	3.462422	
602		1.000000 x	1.580061 =	1.580061	
701	1	1.000000 x	4.751600 =	4.751600	

			T.E =	9.794083	
1322	1322				
112		.200000 x	17.312112 =	3.462422	
701	2	1.000000 x	4.472094 =	4.472094	
603		1.000000 x	6.796685 =	6.796685	

			T.E =	14.731201	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
112		.100000 x	17.312112 =	1.731211	
111		.100000 x	15.741598 =	1.574160	

			T.E =	38.305371	
2110	2110				
712		.500000 x	3.418085 =	1.709043	
608		1.000000 x	12.844408 =	12.844408	
702		1.000000 x	3.016606 =	3.016606	
701	4	1.000000 x	4.192588 =	4.192588	

			T.E =	21.762645	
2120	2120				
712		.500000 x	3.418085 =	1.709043	
603		1.000000 x	6.796685 =	6.796685	
702		1.000000 x	3.016606 =	3.016606	
701	2	1.000000 x	4.472094 =	4.472094	

			T.E =	15.994428	
2130	2130				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.016606 =	3.016606	
604		1.000000 x	7.636467 =	7.636467	
701	2	1.000000 x	4.472094 =	4.472094	

			T.E =	16.834210	

2140	2140				
712		.500000 x	3.418085 =	1.709043	
701	2	1.000000 x	4.472094 =	4.472094	
702		1.000000 x	3.016606 =	3.016606	
605		1.000000 x	11.469962 =	11.469962	

			T.E =	20.667705	
2210	2210				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.016606 =	3.016606	
701	2	1.000000 x	4.472094 =	4.472094	
609		1.050000 x	19.714881 =	20.700625	

			T.E =	29.898368	
2220	2220				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.016606 =	3.016606	
701	2	1.000000 x	4.472094 =	4.472094	
609		1.150000 x	19.714881 =	22.672113	

			T.E =	31.869856	
2230	2230				
111		.200000 x	15.741598 =	3.148320	
609		1.200000 x	19.714881 =	23.657857	
701	2	1.000000 x	4.472094 =	4.472094	

			T.E =	31.278271	
2240	2240				
111		.300000 x	15.741598 =	4.722479	
609		1.200000 x	19.714881 =	23.657857	
701	2	1.000000 x	4.472094 =	4.472094	

			T.E =	32.852431	
2310	2310				
612		1.000000 x	18.495645 =	18.495645	
701	3	1.000000 x	4.360292 =	4.360292	
703		1.000000 x	6.029603 =	6.029603	

			T.E =	28.885540	
2320	2320				
613		1.000000 x	26.970305 =	26.970305	
703		1.000000 x	6.029603 =	6.029603	
701	3	1.000000 x	4.360292 =	4.360292	

			T.E =	37.360200	

2330	2330				
614		1.000000 x	35.254419 =	35.254419	
703		1.000000 x	6.029603 =	6.029603	
701	3	1.000000 x	4.360292 =	4.360292	

				T.E =	45.644314
2340	2340				
615		1.000000 x	46.083637 =	46.083637	
703		1.000000 x	6.029603 =	6.029603	
701	3	1.000000 x	4.360292 =	4.360292	

				T.E =	56.473532
2350	2350				
616		1.000000 x	62.346384 =	62.346384	
703		1.000000 x	6.029603 =	6.029603	
701	3	1.000000 x	4.360292 =	4.360292	

				T.E =	72.736279
2410	2410				
617		1.000000 x	16.550707 =	16.550707	
703		1.000000 x	6.029603 =	6.029603	

				T.E =	22.580310
2420	2420				
618		1.000000 x	20.390472 =	20.390472	
703		1.000000 x	6.029603 =	6.029603	

				T.E =	26.420075
2430	2430				
619		1.000000 x	26.481132 =	26.481132	
703		1.000000 x	6.029603 =	6.029603	

				T.E =	32.510735
2440	2440				
620		1.000000 x	33.101415 =	33.101415	
703		1.000000 x	6.029603 =	6.029603	

				T.E =	39.131018
2450	2450				
621		1.000000 x	43.958679 =	43.958679	
703		1.000000 x	6.029603 =	6.029603	

				T.E =	49.988282

3110	1	3110	1			
	3110A 1			1.000000 x	128.505129 =	128.505129
	3110B			1.000000 x	16.109832 =	16.109832

					T.E =	144.614961
3110	2	3110	2			
	3110A 2			1.000000 x	135.636617 =	135.636617
	3110B			1.000000 x	16.109832 =	16.109832

					T.E =	151.746449
3110	3	3110	3			
	3110A 3			1.000000 x	137.779013 =	137.779013
	3110B			1.000000 x	16.109832 =	16.109832

					T.E =	153.888845
3110	4	3110	4			
	3110A 4			1.000000 x	144.910501 =	144.910501
	3110B			1.000000 x	16.109832 =	16.109832

					T.E =	161.020333
3120	1	3120	1			
	3120A 1			1.000000 x	128.505129 =	128.505129
	3120B			1.000000 x	17.560782 =	17.560782

					T.E =	146.065911
3120	2	3120	2			
	3120A 2			1.000000 x	135.636617 =	135.636617
	3120B			1.000000 x	17.560782 =	17.560782

					T.E =	153.197399
3120	3	3120	3			
	3120A 3			1.000000 x	137.779013 =	137.779013
	3120B			1.000000 x	17.560782 =	17.560782

					T.E =	155.339795
3120	4	3120	4			
	3120A 4			1.000000 x	144.910501 =	144.910501
	3120B			1.000000 x	17.560782 =	17.560782

					T.E =	162.471283

3210 1	3210 1				
3210A 1		1.000000 x	118.087780 =		118.087780
3210B		1.000000 x	16.109832 =		16.109832

			T.E =		134.197612
3210 2	3210 2				
3210A 2		1.000000 x	123.792970 =		123.792970
3210B		1.000000 x	16.109832 =		16.109832

			T.E =		139.902802
3210 3	3210 3				
3210A 3		1.000000 x	125.506887 =		125.506887
3210B		1.000000 x	16.109832 =		16.109832

			T.E =		141.616719
3210 4	3210 4				
3210A 4		1.000000 x	131.212077 =		131.212077
3210B		1.000000 x	16.109832 =		16.109832

			T.E =		147.321909
3210 5	3210 5				
3210A 5		1.000000 x	116.840574 =		116.840574
3210B		1.000000 x	16.109832 =		16.109832

			T.E =		132.950406
3210 6	3210 6				
3210A 6		1.000000 x	122.545765 =		122.545765
3210B		1.000000 x	16.109832 =		16.109832

			T.E =		138.655597
3210 7	3210 7				
3210A 7		1.000000 x	124.259682 =		124.259682
3210B		1.000000 x	16.109832 =		16.109832

			T.E =		140.369514
3210 8	3210 8				
3210A 8		1.000000 x	129.964872 =		129.964872
3210B		1.000000 x	16.109832 =		16.109832

			T.E =		146.074704

3220	1	3220	1			
	3220A 1			1.000000 x	118.087780 =	118.087780
	3220B			1.000000 x	17.560782 =	17.560782

					T.E =	135.648562
3220	2	3220	2			
	3220A 2			1.000000 x	123.792970 =	123.792970
	3220B			1.000000 x	17.560782 =	17.560782

					T.E =	141.353752
3220	3	3220	3			
	3220A 3			1.000000 x	125.506887 =	125.506887
	3220B			1.000000 x	17.560782 =	17.560782

					T.E =	143.067669
3220	4	3220	4			
	3220A 4			1.000000 x	131.212077 =	131.212077
	3220B			1.000000 x	17.560782 =	17.560782

					T.E =	148.772859
3220	5	3220	5			
	3220A 5			1.000000 x	116.840574 =	116.840574
	3220B			1.000000 x	17.560782 =	17.560782

					T.E =	134.401356
3220	6	3220	6			
	3220A 6			1.000000 x	122.545765 =	122.545765
	3220B			1.000000 x	17.560782 =	17.560782

					T.E =	140.106547
3220	7	3220	7			
	3220A 7			1.000000 x	124.259682 =	124.259682
	3220B			1.000000 x	17.560782 =	17.560782

					T.E =	141.820464
3220	8	3220	8			
	3220A 8			1.000000 x	129.964872 =	129.964872
	3220B			1.000000 x	17.560782 =	17.560782

					T.E =	147.525654

3300	1	3300	1			
	3300A	1		1.000000 x	180.591892 =	180.591892
	3300B	1		1.000000 x	16.109832 =	16.109832

					T.E =	196.701724
3300	2	3300	2			
	3300A	1		1.000000 x	180.591892 =	180.591892
	3300B	2		1.000000 x	17.560782 =	17.560782

					T.E =	198.152674
3300	3	3300	3			
	3300A	2		1.000000 x	187.723380 =	187.723380
	3300B	1		1.000000 x	16.109832 =	16.109832

					T.E =	203.833212
3300	4	3300	4			
	3300A	2		1.000000 x	187.723380 =	187.723380
	3300B	2		1.000000 x	17.560782 =	17.560782

					T.E =	205.284162
3300	5	3300	5			
	3300A	3		1.000000 x	189.865776 =	189.865776
	3300B	1		1.000000 x	16.109832 =	16.109832

					T.E =	205.975608
3300	6	3300	6			
	3300A	3		1.000000 x	189.865776 =	189.865776
	3300B	2		1.000000 x	17.560782 =	17.560782

					T.E =	207.426558
3300	7	3300	7			
	3300A	4		1.000000 x	196.997264 =	196.997264
	3300B	1		1.000000 x	16.109832 =	16.109832

					T.E =	213.107096
3300	8	3300	8			
	3300A	4		1.000000 x	196.997264 =	196.997264
	3300B	2		1.000000 x	17.560782 =	17.560782

					T.E =	214.558046

3400 1	3400 1				
3400A 1		1.000000 x	192.871060 =		192.871060
3400B 1		1.000000 x	10.739888 =		10.739888
			T.E =		203.610948
3400 2	3400 2				
3400A 1		1.000000 x	192.871060 =		192.871060
3400B 2		1.000000 x	11.707188 =		11.707188
			T.E =		204.578248
3400 3	3400 3				
3400A 2		1.000000 x	200.002548 =		200.002548
3400B 1		1.000000 x	10.739888 =		10.739888
			T.E =		210.742436
3400 4	3400 4				
3400A 2		1.000000 x	200.002548 =		200.002548
3400B 2		1.000000 x	11.707188 =		11.707188
			T.E =		211.709736
3400 5	3400 5				
3400A 3		1.000000 x	202.144944 =		202.144944
3400B 1		1.000000 x	10.739888 =		10.739888
			T.E =		212.884832
3400 6	3400 6				
3400A 3		1.000000 x	202.144944 =		202.144944
3400B 2		1.000000 x	11.707188 =		11.707188
			T.E =		213.852132
3400 7	3400 7				
3400A 4		1.000000 x	209.276432 =		209.276432
3400B 1		1.000000 x	10.739888 =		10.739888
			T.E =		220.016320
3400 8	3400 8				
3400A 4		1.000000 x	209.276432 =		209.276432
3400B 2		1.000000 x	11.707188 =		11.707188
			T.E =		220.983620

4110	1	4110	1			
	4110A 1			1.000000 x	196.870023 =	196.870023
	4110B			.025000 x	1,577.765644 =	39.444141

					T.E =	236.314164
4110	2	4110	2			
	4110A 2			1.000000 x	204.001511 =	204.001511
	4110B			.025000 x	1,577.765644 =	39.444141

					T.E =	243.445652
4110	3	4110	3			
	4110A 3			1.000000 x	206.143907 =	206.143907
	4110B			.025000 x	1,577.765644 =	39.444141

					T.E =	245.588048
4110	4	4110	4			
	4110A 4			1.000000 x	213.275395 =	213.275395
	4110B			.025000 x	1,577.765644 =	39.444141

					T.E =	252.719536
4120	1	4120	1			
	4120A 1			1.000000 x	160.881183 =	160.881183
	4120B			1.000000 x	63.110626 =	63.110626

					T.E =	223.991809
4120	2	4120	2			
	4120A 2			1.000000 x	177.996754 =	177.996754
	4120B			1.000000 x	63.110626 =	63.110626

					T.E =	241.107380
4130	1	4130	1			
	4130A 1			1.000000 x	142.478285 =	142.478285
	4130B			1.000000 x	63.110626 =	63.110626

					T.E =	205.588911
4130	2	4130	2			
	4130A 2			1.000000 x	149.609773 =	149.609773
	4130B			1.000000 x	63.110626 =	63.110626

					T.E =	212.720399

4130	3	4130	3				
4130A	3			1.000000 x	151.752169 =	151.752169	
4130B				1.000000 x	63.110626 =	63.110626	

						T.E =	214.862795
4130	4	4130	4				
4130A	4			1.000000 x	158.883657 =	158.883657	
4130B				1.000000 x	63.110626 =	63.110626	

						T.E =	221.994283
4210	1	4210	1				
4210A	1			1.000000 x	41.754514 =	41.754514	
4210B				1.000000 x	143.445697 =	143.445697	

						T.E =	185.200211
4210	2	4210	2				
4210A	2			1.000000 x	46.033407 =	46.033407	
4210B				1.000000 x	143.445697 =	143.445697	

						T.E =	189.479104
4210	3	4210	3				
4210A	3			1.000000 x	37.662122 =	37.662122	
4210B				1.000000 x	143.445697 =	143.445697	

						T.E =	181.107819
4210	4	4210	4				
4210A	4			1.000000 x	41.941015 =	41.941015	
4210B				1.000000 x	143.445697 =	143.445697	

						T.E =	185.386712
4220B	1	4220B	1				
319				.020000 x	21.440000 =	.428800	
701	2			.320000 x	4.472094 =	1.431070	
601				.320000 x	23.612397 =	7.555967	
4220A	1			.800000 x	107.071622 =	85.657298	
714				1.150000 x	7.207995 =	8.289194	
111				.400000 x	15.741598 =	6.296639	

						T.E =	109.658968

4220B 2	4220B 2			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.207995 =	8.289194
701 2		.320000 x	4.472094 =	1.431070
601		.320000 x	23.612397 =	7.555967
4220A 2		.800000 x	114.203110 =	91.362488

T.E = 115.364159

4220B 3	4220B 3			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.472094 =	1.431070
601		.320000 x	23.612397 =	7.555967
111		.400000 x	15.741598 =	6.296639
4220A 3		.800000 x	116.345506 =	93.076405
714		1.150000 x	7.207995 =	8.289194

T.E = 117.078075

4220B 4	4220B 4			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
4220A 4		.800000 x	123.476994 =	98.781595
701 2		.320000 x	4.472094 =	1.431070
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.207995 =	8.289194

T.E = 122.783266

4220B 5	4220B 5			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.472094 =	1.431070
609		.320000 x	19.714881 =	6.308762
4220A 1		.800000 x	107.071622 =	85.657298
714		1.150000 x	7.207995 =	8.289194
111		.400000 x	15.741598 =	6.296639

T.E = 108.411763

4220B 6	4220B 6			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.207995 =	8.289194
701 2		.320000 x	4.472094 =	1.431070
609		.320000 x	19.714881 =	6.308762
4220A 2		.800000 x	114.203110 =	91.362488

T.E = 114.116953

4220B 7	4220B 7			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.472094 =	1.431070
609		.320000 x	19.714881 =	6.308762
111		.400000 x	15.741598 =	6.296639
4220A 3		.800000 x	116.345506 =	93.076405
714		1.150000 x	7.207995 =	8.289194

T.E = 115.830870

4220B 8	4220B 8			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
4220A 4		.800000 x	123.476994 =	98.781595
701 2		.320000 x	4.472094 =	1.431070
609		.320000 x	19.714881 =	6.308762
714		1.150000 x	7.207995 =	8.289194

T.E = 121.536061

4230 1	4230 1			
221		250.000000 x	.098900 =	24.725000
701 5		.250000 x	2.795059 =	.698765
701 2		.500000 x	4.472094 =	2.236047
701 2		.800000 x	4.472094 =	3.577675
630		.250000 x	3.077561 =	.769390
607		.500000 x	9.715925 =	4.857963
606		.800000 x	8.872844 =	7.098275
407		.040000 x	718.602575 =	28.744103
714		1.150000 x	7.207995 =	8.289194
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
319		.020000 x	21.440000 =	.428800

T.E = 137.411791

4230 2	4230 2			
221		250.000000 x	.098900 =	24.725000
701 5		.250000 x	2.795059 =	.698765
701 4		.500000 x	4.192588 =	2.096294
701 2		.800000 x	4.472094 =	3.577675
630		.250000 x	3.077561 =	.769390
319		.020000 x	21.440000 =	.428800
111		2.000000 x	15.741598 =	31.483196
407		.040000 x	718.602575 =	28.744103
611		.500000 x	24.258407 =	12.129204
606		.800000 x	8.872844 =	7.098275
714		1.150000 x	7.207995 =	8.289194
113		1.200000 x	20.419486 =	24.503383

T.E = 144.543279

4230	3	4230	3			
221				250.000000 x	.098900 =	24.725000
701	5			.250000 x	2.795059 =	.698765
701	4			.800000 x	4.192588 =	3.354070
701	2			.500000 x	4.472094 =	2.236047
630				.250000 x	3.077561 =	.769390
610				.800000 x	20.744705 =	16.595764
607				.500000 x	9.715925 =	4.857963
407				.040000 x	718.602575 =	28.744103
714				1.150000 x	7.207995 =	8.289194
319				.020000 x	21.440000 =	.428800
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196

T.E = 146.685675

4230	4	4230	4			
221				250.000000 x	.098900 =	24.725000
701	5			.250000 x	2.795059 =	.698765
701	4			.500000 x	4.192588 =	2.096294
701	4			.800000 x	4.192588 =	3.354070
630				.250000 x	3.077561 =	.769390
319				.020000 x	21.440000 =	.428800
113				1.200000 x	20.419486 =	24.503383
407				.040000 x	718.602575 =	28.744103
611				.500000 x	24.258407 =	12.129204
610				.800000 x	20.744705 =	16.595764
714				1.150000 x	7.207995 =	8.289194
111				2.000000 x	15.741598 =	31.483196

T.E = 153.817163

4240	1	4240	1			
221				300.000000 x	.098900 =	29.670000
701	5			.250000 x	2.795059 =	.698765
701	2			.500000 x	4.472094 =	2.236047
701	2			.800000 x	4.472094 =	3.577675
630				.250000 x	3.077561 =	.769390
607				.500000 x	9.715925 =	4.857963
606				.800000 x	8.872844 =	7.098275
407				.040000 x	718.602575 =	28.744103
714				1.150000 x	7.207995 =	8.289194
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196
319				.020000 x	21.440000 =	.428800

T.E = 142.356791

4240	2	4240	2			
221				300.000000 x	.098900 =	29.670000
701	5			.250000 x	2.795059 =	.698765
701	4			.500000 x	4.192588 =	2.096294
701	2			.800000 x	4.472094 =	3.577675
630				.250000 x	3.077561 =	.769390
319				.020000 x	21.440000 =	.428800
111				2.000000 x	15.741598 =	31.483196
407				.040000 x	718.602575 =	28.744103
611				.500000 x	24.258407 =	12.129204
606				.800000 x	8.872844 =	7.098275
714				1.150000 x	7.207995 =	8.289194
113				1.200000 x	20.419486 =	24.503383

T.E = 149.488279

4240	3	4240	3			
221				300.000000 x	.098900 =	29.670000
701	5			.250000 x	2.795059 =	.698765
701	4			.800000 x	4.192588 =	3.354070
701	2			.500000 x	4.472094 =	2.236047
630				.250000 x	3.077561 =	.769390
610				.800000 x	20.744705 =	16.595764
607				.500000 x	9.715925 =	4.857963
407				.040000 x	718.602575 =	28.744103
714				1.150000 x	7.207995 =	8.289194
319				.020000 x	21.440000 =	.428800
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196

T.E = 151.630675

4240	4	4240	4			
221				300.000000 x	.098900 =	29.670000
319				.020000 x	21.440000 =	.428800
113				1.200000 x	20.419486 =	24.503383
714				1.150000 x	7.207995 =	8.289194
701	5			.250000 x	2.795059 =	.698765
701	4			.500000 x	4.192588 =	2.096294
701	4			.800000 x	4.192588 =	3.354070
630				.250000 x	3.077561 =	.769390
611				.500000 x	24.258407 =	12.129204
610				.800000 x	20.744705 =	16.595764
407				.040000 x	718.602575 =	28.744103
111				2.000000 x	15.741598 =	31.483196

T.E = 158.762163

4300	1	4300	1			
4300A	1			1.000000 x	29.374598 =	29.374598
4300B				1.000000 x	11.042645 =	11.042645

T.E = 40.417243

ΑΤΛΕ		1ο Τρίμηνο του 2010		Σελ.	49
				Ημ/νία	16/06/2011
4300	2	4300	2		
4300A	2			1.000000 x	30.800896 =
4300B				1.000000 x	11.042645 =

				T.E =	41.843541
4300	3	4300	3		
4300A	3			1.000000 x	31.229375 =
4300B				1.000000 x	11.042645 =

				T.E =	42.272020
4300	4	4300	4		
4300A	4			1.000000 x	32.655673 =
4300B				1.000000 x	11.042645 =

				T.E =	43.698318
4400		4400			
251				1.050000 x	.559800 =
113				.050000 x	20.419486 =

				T.E =	1.608764
4500		4500			
251				1.050000 x	.559800 =
113				.100000 x	20.419486 =
114				.100000 x	17.312112 =

				T.E =	4.360950
4600		4600			
256				1.000000 x	3.600000 =
113				.100000 x	20.419486 =

				T.E =	5.641949
4700		4700			
253				1.000000 x	3.800000 =
113				.100000 x	20.419486 =

				T.E =	5.841949